

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA ISAAC NEWTON TELESCOPE INT 1

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
3735 MATBRO TELESCOPIC FORK LIFT	2700 KGS	RED 2651
HOOTER FOR REVERSING + FLASHING LAMP SHOULD BE FITTED OFF SIDE FRONT INDICATOR LENSE BROKEN DAMAGE TO SEALS ON NEAR SIDE HYDRAULIC LOCKING PIN	AS BELOW AS ABOVE	
LPL 093 (CB/204002) WIRE ROPE SLING 4.5M EWL	5 TON	CO5
NONE	AS BELOW	
LPL 118 (71535) RATCLIFF TAIL LIFT FITTED TO MERCEDES LORRY	1000 KGS	4837-029
NONE	AS BELOW	
LPL 024 (3W2266) 22MM WIRE ROPE SLING 25' TEE	4 TON	10/3W2266
NONE	AS BELOW	
LPL 088 (13599) PELLOBY POST MOUNTED SWING JIB	2 TONNE	13599
NONE	AS BELOW	
LPL 089 (10-1001-NC2) MORRIS 360 ELECTRIC CHAIN HOIST ON ABOVE	2 TONNE	13599
NONE	AS BELOW	
LPL 090 CHAIN WORN BUT SERVICEABLE 2.5M MIRROR CLAMP SUPPORT	2000 LBS	CERTIFICATE FOUND NO NUMBER
NONE	AS BELOW	
LPL 097 (EN3354) A AND G LIFT FRAME (2.5M TEL) CONTROL CIRCUIT VIA LIMIT SWITCHES ARE 240V AC. FINAL WIRING TO LIMIT SWITCHES IS EXPOSED AND DOES NOT COMPLY WITH CURRENT REGULATIONS. REMEDY IS TO REPLACE LIMIT SWITCHES TO ENCLOSED CABLE TYPE OR REPLACE CONTROL CIRCUIT.	1 TONNE	R328
	AS BELOW	
	AS ABOVE	

I certify that on 25.09.00 - 02.10.00
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA ISAAC NEWTON TELESCOPE INT 2

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE RED
LPL 111 LIFTING BEAM WITH CENTRE LIFTING EYE AND 2 POINT LIFTING LUGS AT 34" CENTRES	320 KGS AS BELOW AS ABOVE	2651
NONE	AS ABOVE	
LPL 124 KONE ELECTRIC WIRE ROPE HOIST WITH FIXED SUSPENSION TO DOME. RAISING AND LOWERING THROUGH 4 DIVERTER SHEAVES	5 TONNE AS BELOW AS ABOVE	92792600
NO SAFE ACCESS TO INSPECT SHEAVE BLOCKS	AS ABOVE	
LPL 128 (20-11-44993) 30615 POST MOUNTED SWING JIB C/W MORRIS ELECTRIC CHAIN HOIST	500 KGS AS BELOW AS ABOVE	984 7023
NONE - NO HANDLE FOR JACK	AS ABOVE	
LPL 374 (A1) M12 COLLARED EYEBOLT	0.4 TONNE AS BELOW	55909/ 24/86
NOT LOCATED (4)	AS ABOVE	
LPL827 123449 HYDRAULIC STACKER TRUCK	1000 KGS AS BELOW AS ABOVE	TEST CERTIFICATE SHOULD BE HELD ON FILE
SAFETY GUARD BROKEN TOP LEFT CORNER.	AS BELOW	
NONE	AS ABOVE	
LPL 536 MORRIS ELECTRIC CHAIN HOIST	1000 KGS AS BELOW	13599
NONE	AS ABOVE	
LPL 537 OVERHEAD RUNWAY BEAM	1000 KGS AS BELOW AS ABOVE	
NONE	AS ABOVE	
LPL825 123225 HYDRAULIC GRATING SHUTTER INTERLOCK LIFTING TABLE	NO SWL MARKED AS BELOW AS ABOVE	R328
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA ISAAC NEWTON TELESCOPE INT 3

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
NO SERIAL NUMBER 2 X CABLE DRUM JACK RG GIBBINS	5 TONNE AS BELOW	RED 2651
NONE	AS ABOVE	
1 ALBA HAND WINCH C/W WIRE ROPE BULLDOG GRIPS SHOULD BE CHECKED FOR TIGHTNESS. GRIPS SHOULD BE 8MM (5/16") NOT 3/8"	500 KGS AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	
2 ALBA HAND WINCH C/W WIRE ROPE	500 KGS AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
AS ABOVE	AS ABOVE	
3 ALBA HAND WINCH C/W WIRE ROPE	0.4 TONNE AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
AS ABOVE	AS ABOVE	
4 ALBA HAND WINCH C/W WIRE ROPE	500KGS AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
AS ABOVE	AS ABOVE	
LPL893 EW 55245 SLINGSBY LIFTING CRADLE 4 POINT LIFT	1300LBS AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	
A 10075 MOBILE HYDRAULIC LIFT TABLE	1 TON AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

[Handwritten signature]

ENGINEER/SURVEILLOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA ISAAC NEWTON TELESCOPE INT 4

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR	
		CODE	
LPL824 T1388	MOBILE HYDRAULIC LIFTING TABLE	2000 KGS	RED
NONE		AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
LPL826 TB 122405	CENTRE POINT PICK UP MIRROR SPIDER LIFT	5 TONNE	TEST
NONE		AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
901155	WESCO DRUM LIFTER MODEL DL55	800 KGS	TEST
NONE		AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
507849	STOCKA HAND PALLET TRUCK	2300 KGS	TEST
NOT LOCATED		AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
LPL823 123460	STOCKA HAND PALLET TRUCK	2300 KGS	
NONE		AS BELOW	
LESL16183	SMALL LIFTING BEAM CENTRE LIFTING C/W 4 CAPTIVE DROP CHAINS AND ANCILLARY PIECES	250 KGS	
NOT LOCATED		AS BELOW	
LPL915 11029	FK1 BRADBURY VEHICLE LIFT	2.5 TONNE	TEST
NONE		AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
42127	VIKING ENGINE CRANE	0.5 TONNE	TEST
NONE, SLIGHT DAMAGE TO RELEASE HANDLE ON VALVE		AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
		AS ABOVE	FILE

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA ISAAC NEWTON TELESCOPE INT 5

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL828 9597 LIFTING BEAM (SHUTTER WHEEL CONTROL)	300 KGS AS BELOW AS ABOVE	RED 51908
NONE LPL707-E1177 GOODS CAGE 108 X 151 X 105CM WHT	500 KGS AS BELOW AS ABOVE	
NONE 4 X KONE ELECTRIC WIRE ROPE HOISTS 2 LOCATED ON UPPER SHUTTER DOOR 2 LOCATED ON LOWER SHUTTER DOOR	AS BELOW AS ABOVE	TEST CERTIFICATE SHOULD BE HELD ON FILE
LEFT HAND SIDE LOWER SHUTTER WIRE ROPE HAS BROKEN STRANDS CAUSE SHOULD BE INVESTIGATED AND RECTIFIED		
LPL834 596371 9MM DIA X 11" WIRE ROPE SLING	.76 TONNES	
NONE LPL835 5S65/1 9MM DIA X 11" WIRE ROPE SLING	.76 TONNES	
NONE 3374H H.T. DEE SHACKLE TO BS3032	1 TON	
NOT LOCATED (3)		

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification..... ENGINEER SURVEYOR