

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 31

| Distinguishing number and description<br>Defects and observations | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE                          |
|---|--|---|
| O131 2M CIRC POLYESTER ROUNDSLING                                 | 1 TONNE<br>AS BELOW<br>AS ABOVE                      | RED                                     |
| SCRAPED<br>LPL822 R139205 01603 SUPER CLAMP                       | 1 TONNE<br>AS BELOW<br>AS ABOVE                      | HEY13891                                |
| NONE<br>LPL821 R139205 01604 SUPER CLAMP                          | 1 TONNE<br>AS BELOW<br>AS ABOVE                      | HEY13886                                |
| NONE<br>14809 6M CIRC POLYESTER ROUNDSLING                        | 3 TONNE<br>AS BELOW<br>AS ABOVE                      | TEST CERTIFICATE SHOULD BE HELD ON FILE |
| NONE<br>99703 1/2" LARGE DEE SHACKLE TO BS3032                    | 15 CWT<br>AS BELOW<br>AS ABOVE                       |   |
| NOT LOCATED (2)<br>SH265 ALLOY STEEL DEE SHACKLE TO US SPEC       | 2 TON<br>AS BELOW<br>AS ABOVE                        | TEST CERTIFICATE SHOULD BE HELD ON FILE |
| NOT LOCATED (2)<br>127MA M16 COLLARED EYEBOLT                     | 0.63 TONNE<br>AS BELOW<br>AS ABOVE                   | TEST CERTIFICATE SHOULD BE HELD ON FILE |
| NONE<br>12819 4M CIRC POLYESTER ROUNDSLING                        | 2 TONNE<br>AS BELOW<br>AS ABOVE                      | TEST CERTIFICATE SHOULD BE HELD ON FILE |
| NONE  |  |   |

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 31

| Distinguishing number and description<br>Defects and observations | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE                          |
|---|--|---|
| O131 2M CIRC POLYESTER ROUNDSLING                                 | 1 TONNE<br>AS BELOW<br>AS ABOVE                      | RED                                     |
| SCRAPED<br>LPL822 R139205 01603 SUPER CLAMP                       | 1 TONNE<br>AS BELOW<br>AS ABOVE                      | HEY13891                                |
| NONE<br>LPL821 R139205 01604 SUPER CLAMP                          | 1 TONNE<br>AS BELOW<br>AS ABOVE                      | HEY13886                                |
| NONE<br>14809 6M CIRC POLYESTER ROUNDSLING                        | 3 TONNE<br>AS BELOW<br>AS ABOVE                      | TEST CERTIFICATE SHOULD BE HELD ON FILE |
| NONE<br>99703 1/2" LARGE DEE SHACKLE TO BS3032                    | 15 CWT<br>AS BELOW<br>AS ABOVE                       |   |
| NOT LOCATED (2)<br>SH265 ALLOY STEEL DEE SHACKLE TO US SPEC       | 2 TON<br>AS BELOW<br>AS ABOVE                        | TEST CERTIFICATE SHOULD BE HELD ON FILE |
| NOT LOCATED (2)<br>127MA M16 COLLARED EYEBOLT                     | 0.63 TONNE<br>AS BELOW<br>AS ABOVE                   | TEST CERTIFICATE SHOULD BE HELD ON FILE |
| NONE<br>12819 4M CIRC POLYESTER ROUNDSLING                        | 2 TONNE<br>AS BELOW<br>AS ABOVE                      | TEST CERTIFICATE SHOULD BE HELD ON FILE |
| NONE  |  |   |

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 33

| Distinguishing number and description<br>Defects and observations | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE<br><br>RED                             |
|---|--|---|
| O131 2M CIRC POLYESTER ROUNDSLING                                 | 1 TONNE<br><br>AS BELOW<br><br>AS ABOVE              |   |
| DUPLICATED<br>LPL698 15048 1M CIRC POLYESTER ROUNDSLING           | 2 TONNE<br><br>AS BELOW<br><br>AS ABOVE              |   |
| NONE<br>LPL695 123437 POLYESTER ROUNDSLING                        | 1 TONNE<br><br>AS BELOW<br><br>AS ABOVE              |   |
| NONE<br>14809 6M CIRC POLYESTER ROUNDSLING                        | 3 TONNE<br><br>AS BELOW<br><br>AS ABOVE              | TEST CERT-<br>IFICATE<br>SHOULD BE<br>HELD ON<br>FILE |
| NONE<br>36032 1/2" LARGE DEE SHACKLE TO BS3032                    | 15 CWT<br><br>AS BELOW<br><br>AS ABOVE               |   |
| NOT LOCATED ( 6 )<br>SH265 ALLOY STEEL DEE SHACKLE TO US SPEC     | 2 TON<br><br>AS BELOW<br><br>AS ABOVE                | TEST CERT-<br>IFICATE<br>SHOULD BE<br>HELD ON<br>FILE |
| DUPLICATED<br>127MA M16 COLLARED EYEBOLT                          | 0.63 TONNE<br><br>AS BELOW<br><br>AS ABOVE           | TEST CERT-<br>IFICATE<br>SHOULD BE<br>HELD ON<br>FILE |
| NONE<br>12819 4M CIRC POLYESTER ROUNDSLING                        | 2 TONNE<br><br>AS BELOW<br><br>AS ABOVE              | TEST CERT-<br>IFICATE<br>SHOULD BE<br>HELD ON<br>FILE |
| NONE  |  |   |

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 34

| Distinguishing number and description<br>Defects and observations |       |              | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE<br><br>RED |
|---|-------|--------------|--|---------------------------|
| LPL876  | GER23 | BOTTLE SCREW | 7.5 CWT<br><br>AS BELOW<br><br>AS ABOVE              |                           |
| NONE  |       |              |  |                           |
| LPL883  | GER23 | BOTTLE SCREW | 7.5 CWT<br><br>AS BELOW<br><br>AS ABOVE              |                           |
| NONE  |       |              |  |                           |
| LPL877  | 25FL  | BOTTLE SCREW | 3 CWT<br><br>AS BELOW<br><br>AS ABOVE                |                           |
| NONE  |       |              |  |                           |
| LPL878  | 25FL  | BOTTLE SCREW | 3 CWT<br><br>AS BELOW<br><br>AS ABOVE                |                           |
| NONE  |       |              |  |                           |
| LPL879  | 25FL  | BOTTLE SCREW | 3 CWT<br><br>AS BELOW<br><br>AS ABOVE                |                           |
| NONE  |       |              |  |                           |
| LPL880  | 25FL  | BOTTLE SCREW | 2 CWT<br><br>AS BELOW<br><br>AS ABOVE                |                           |
| NONE  |       |              |  |                           |
| LPL881  | 25FL  | BOTTLE SCREW | 2 CWT<br><br>AS BELOW<br><br>AS ABOVE                |                           |
| NONE  |       |              |  |                           |
| LPL882  | 25FL  | BOTTLE SCREW | 2 CWT<br><br>AS BELOW<br><br>AS ABOVE                |                           |

I certify that on 25.09.00 - 02.10.00  
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 35

| Distinguishing number and description<br>Defects and observations                      | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE |
|--|--|----------------|
|  |  | RED            |
| LPL916 BCG 33<br>H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN         | 1 TON<br>AS BELOW<br>AS ABOVE                        |                |
| NONE<br>LPL917 BCG 33<br>H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1 TON<br>AS BELOW<br>AS ABOVE                        |                |
| NONE<br>LPL918 BCG 33<br>H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1 TON<br>AS BELOW<br>AS ABOVE                        |                |
| NONE<br>LPL919 BCG 33<br>H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1 TON<br>AS BELOW<br>AS ABOVE                        |                |
| NONE<br>LPL868 ULG 39<br>H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1 TON<br>AS BELOW<br>AS ABOVE                        |                |
| NONE<br>LPL869 EAG 33<br>H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1 TON<br>AS BELOW<br>AS ABOVE                        |                |
| NONE<br>LPL870 UCG 33<br>H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1 TON<br>AS BELOW<br>AS ABOVE                        |                |
| NONE<br>LPL871 UCG 39<br>H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1 TON<br>AS BELOW<br>AS ABOVE                        |                |

I certify that on 25.09.00 - 02.10.00  
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier  
Address


ISAAC NEWTON GROUP OF TELESCOPES  
LA PALMA LIFTING TACKLE STORES LTS 36

| Distinguishing number and description<br>Defects and observations |        | Safe working load<br>Date of examination<br>Location          | COLOUR<br>CODE<br><br>RED               |
|---|--------|---|---|
| LPL872  | 8281   | H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 2 TON<br><br>AS BELOW<br><br>AS ABOVE   |
| NONE  |        |   |   |
| LPL873  | 8282   | H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 2 TON<br><br>AS BELOW<br><br>AS ABOVE   |
| NONE  |        |   |   |
| LPL874  | 8283   | H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 2 TON<br><br>AS BELOW<br><br>AS ABOVE   |
| NONE  |        |   |   |
| LPL875  | 8284   | H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 2 TON<br><br>AS BELOW<br><br>AS ABOVE   |
| NONE  |        |   |   |
| LPL920  | CE 828 | H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1.5 TON<br><br>AS BELOW<br><br>AS ABOVE |
| NONE  |        |   |   |
| LPL921  | CE 828 | H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1.5 TON<br><br>AS BELOW<br><br>AS ABOVE |
| NONE  |        |   |   |
| LPL922  | CE 828 | H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1.5 TON<br><br>AS BELOW<br><br>AS ABOVE |
| NONE  |        |   |   |
| LPL923  | CE 828 | H.T. SAFETY BOW SHACKLE TO BS3032<br>C/W NUT BOLT & SPLIT PIN | 1.5 TON<br><br>AS BELOW<br><br>AS ABOVE |

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 37

| Distinguishing number and description<br>Defects and observations |     | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE<br><br>RED        |      |
|---|-----|--|----------------------------------|------|
| LPL852  | E 1 | M8 COLLARED EYEBOLT TO BS4278/1                      | 0.15 TON<br>AS BELOW<br>AS ABOVE | 7431 |
| NONE  |     |  |                                  |      |
| LPL853  | E 2 | M8 COLLARED EYEBOLT TO BS4278/1                      | 0.15 TON<br>AS BELOW<br>AS ABOVE | 7431 |
| NONE  |     |  |                                  |      |
| LPL854  | E 3 | M8 COLLARED EYEBOLT TO BS4278/1                      | 0.15 TON<br>AS BELOW<br>AS ABOVE | 7431 |
| NONE  |     |  |                                  |      |
| LPL855  | E 4 | M8 COLLARED EYEBOLT TO BS4278/1                      | 0.15 TON<br>AS BELOW<br>AS ABOVE | 7431 |
| NONE  |     |  |                                  |      |
| LPL856  | E 5 | M8 COLLARED EYEBOLT TO BS4278/1                      | 1.5 TON<br>AS BELOW<br>AS ABOVE  | 7431 |
| NONE  |     |  |                                  |      |
| LPL857  | E 6 | M8 COLLARED EYEBOLT TO BS4278/1                      | 1.5 TON<br>AS BELOW<br>AS ABOVE  | 7431 |
| NONE  |     |  |                                  |      |
| LPL858  | E 7 | M8 COLLARED EYEBOLT TO BS4278/1                      | 1.5 TON<br>AS BELOW<br>AS ABOVE  | 7431 |
| NONE  |     |  |                                  |      |
| LPL859  | E 8 | M8 COLLARED EYEBOLT TO BS4278/1                      | 1.5 TON<br>AS BELOW<br>AS ABOVE  | 7431 |

I certify that on 25.09.00 - 02.10.00  
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 38

| Distinguishing number and description<br>Defects and observations | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE |
|---|--|----------------|
| LPL836 T 31 M10 COLLARED EYEBOLT TO BS4278/1                      | 0.33 TONNES<br>AS BELOW<br>AS ABOVE                  | RED<br>7432    |
| NOT LOCATED (1)<br>LPL837 T 32 M10 COLLARED EYEBOLT TO BS4278/1   | 0.33 TONNES<br>AS BELOW<br>AS ABOVE                  | 7432           |
| NOT LOCATED (1)<br>LPL838 T 33 M10 COLLARED EYEBOLT TO BS4278/1   | 0.33 TONNES<br>AS BELOW<br>AS ABOVE                  | 7432           |
| NOT LOCATED (1)<br>LPL839 T 34 M10 COLLARED EYEBOLT TO BS4278/1   | 0.33 TONNES<br>AS BELOW<br>AS ABOVE                  | 7432           |
| NOT LOCATED (1)<br>LPL840 T 35 M10 COLLARED EYEBOLT TO BS4278/1   | 0.33 TONNES<br>AS BELOW<br>AS ABOVE                  | 7432           |
| NOT LOCATED (2)<br>LPL841 T 36 M10 COLLARED EYEBOLT TO BS4278/1   | 0.33 TONNES<br>AS BELOW<br>AS ABOVE                  | 7432           |
| NOT LOCATED (2)<br>LPL842 T 37 M10 COLLARED EYEBOLT TO BS4278/1   | 0.33 TONNES<br>AS BELOW<br>AS ABOVE                  | 7432           |
| NOT LOCATED (2)<br>LPL843 T 38 M10 COLLARED EYEBOLT TO BS4278/1   | 0.33 TONNES<br>AS BELOW<br>AS ABOVE                  | 7432           |
| NOT LOCATED (2)   |  |                |

I certify that on 25.09.00 - 02.10.00  
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 39

| Distinguishing number and description<br>Defects and observations |     | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE<br><br>RED           |      |
|---|-----|--|-------------------------------------|------|
| LPL844  | G 1 | M12 COLLARED EYEBOLT TO BS4278/1                     | 0.40 TONNES<br>AS BELOW<br>AS ABOVE | 7433 |
| NOT LOCATED (1)   |     |  |                                     |      |
| LPL845  | G 2 | M12 COLLARED EYEBOLT TO BS4278/1                     | 0.40 TONNES<br>AS BELOW<br>AS ABOVE | 7433 |
| NONE  |     |  |                                     |      |
| LPL846  | G 3 | M12 COLLARED EYEBOLT TO BS4278/1                     | 0.40 TONNES<br>AS BELOW<br>AS ABOVE | 7433 |
| NOT LOCATED (1)   |     |  |                                     |      |
| LPL847  | G 4 | M12 COLLARED EYEBOLT TO BS4278/1                     | 0.40 TONNES<br>AS BELOW<br>AS ABOVE | 7433 |
| NONE  |     |  |                                     |      |
| LPL848  | G 5 | M12 COLLARED EYEBOLT TO BS4278/1                     | 0.40 TONNES<br>AS BELOW<br>AS ABOVE | 7433 |
| NONE  |     |  |                                     |      |
| LPL849  | G 6 | M12 COLLARED EYEBOLT TO BS4278/1                     | 0.40 TONNES<br>AS BELOW<br>AS ABOVE | 7433 |
| NONE  |     |  |                                     |      |
| LPL850  | G 7 | M12 COLLARED EYEBOLT TO BS4278/1                     | 0.40 TONNES<br>AS BELOW<br>AS ABOVE | 7433 |
| NOT LOCATED (1)   |     |  |                                     |      |
| LPL851  | G 8 | M12 COLLARED EYEBOLT TO BS4278/1                     | 0.40 TONNES<br>AS BELOW<br>AS ABOVE | 7433 |
| NONE  |     |  |                                     |      |

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 40

| Distinguishing number and description<br>Defects and observations |     | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE<br><br>RED           |      |
|---|-----|--|-------------------------------------|------|
| LPL860  | R 1 | M16 COLLARED EYEBOLT TO BS4278/1                     | 0.80 TONNES<br>AS BELOW<br>AS ABOVE | 7434 |
| NONE  |     |  |                                     |      |
| LPL861  | R 2 | M16 COLLARED EYEBOLT TO BS4278/1                     | 0.80 TONNES<br>AS BELOW<br>AS ABOVE | 7434 |
| NONE  |     |  |                                     |      |
| LPL862  | R 3 | M16 COLLARED EYEBOLT TO BS4278/1                     | 0.80 TONNES<br>AS BELOW<br>AS ABOVE | 7434 |
| NONE  |     |  |                                     |      |
| LPL863  | R 4 | M16 COLLARED EYEBOLT TO BS4278/1                     | 0.80 TONNES<br>AS BELOW<br>AS ABOVE | 7434 |
| NONE  |     |  |                                     |      |
| LPL864  | R 5 | M16 COLLARED EYEBOLT TO BS4278/1                     | 0.80 TONNES<br>AS BELOW<br>AS ABOVE | 7434 |
| NONE  |     |  |                                     |      |
| LPL865  | R 6 | M16 COLLARED EYEBOLT TO BS4278/1                     | 0.80 TONNES<br>AS BELOW<br>AS ABOVE | 7434 |
| NONE  |     |  |                                     |      |
| LPL866  | R 7 | M16 COLLARED EYEBOLT TO BS4278/1                     | 0.80 TONNES<br>AS BELOW<br>AS ABOVE | 7434 |
| NONE  |     |  |                                     |      |
| LPL867  | R 8 | M16 COLLARED EYEBOLT TO BS4278/1                     | 0.80 TONNES<br>AS BELOW<br>AS ABOVE | 7434 |
| NONE  |     |  |                                     |      |

I certify that on 25.09.00 - 02.10.00  
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 41

| Distinguishing number and description<br>Defects and observations | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE<br><br>RED |
|---|--|---------------------------|
| LPL383 M16 COLLARED EYEBOLT TO BS4278/1                           | 0.80 TONNES<br><br>AS BELOW<br><br>AS ABOVE          |                           |
| NONE<br>LPL674 M16 COLLARED EYEBOLT TO BS4278/1                   | 0.80 TONNES<br><br>AS BELOW<br><br>AS ABOVE          |                           |
| NOT LOCATED (1)<br>LPL675 5/8" BSW COLLARED EYEBOLT TO BS529/1    | 0.90 TONS<br><br>AS BELOW<br><br>AS ABOVE            |                           |
| NONE<br>LPL676 5/8" BSW COLLARED EYEBOLT TO BS529/1               | 0.90 TONS<br><br>AS BELOW<br><br>AS ABOVE            |                           |
| NONE<br>LPL677 M16 COLLARED EYEBOLT TO BS4278/1                   | 0.80 TONNES<br><br>AS BELOW<br><br>AS ABOVE          |                           |
| NONE<br>LPL678 5/8" BSW COLLARED EYEBOLT TO BS529/1               | 0.90 TONS<br><br>AS BELOW<br><br>AS ABOVE            |                           |
| NONE<br>LPL679 M16 COLLARED EYEBOLT TO BS4278/1                   | 0.80 TONNES<br><br>AS BELOW<br><br>AS ABOVE          |                           |
| NONE<br>LPL250 M16 COLLARED EYEBOLT TO BS4278/1                   | 0.80 TONNES<br><br>AS BELOW<br><br>AS ABOVE          |                           |
| NOT LOCATED (1)   | AS ABOVE   |                           |

I certify that on 25.09.00 - 02.10.00  
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 42

| Distinguishing number and description<br>Defects and observations        | Safe working load<br>Date of examination<br>Location | COLOUR<br>CODE<br><br>RED |
|--|--|---------------------------|
| LPL289 M16 COLLARED EYEBOLT TO BS4278/1                                  | 0.80 TONNES<br>AS BELOW<br>AS ABOVE                  |                           |
| NONE<br>LPL520 M16 COLLARED EYEBOLT TO BS4278/1<br>LONG SHANK            | 0.80 TONNES<br>AS BELOW<br>AS ABOVE                  |                           |
| NOT LOCATED (1)<br>LPL521 M16 COLLARED EYEBOLT TO BS4278/1<br>LONG SHANK | 0.80 TONNES<br>AS BELOW<br>AS ABOVE                  |                           |
| NOT LOCATED (1)<br>LPL578 M16 COLLARED EYEBOLT TO BS4278/1<br>LONG SHANK | 0.80 TONNES<br>AS BELOW<br>AS ABOVE                  |                           |
| NONE<br>LPL579 M16 COLLARED EYEBOLT TO BS4278/1<br>LONG SHANK            | 0.80 TONNES<br>AS BELOW<br>AS ABOVE                  |                           |
| NONE<br>LPL680 M16 COLLARED EYEBOLT TO BS4278/1<br>LONG SHANK            | 0.80 TONNES<br>AS BELOW<br>AS ABOVE                  |                           |
| NOT LOCATED (2)<br>LPL681 M16 COLLARED EYEBOLT TO BS4278/1<br>LONG SHANK | 0.80 TONNES<br>AS BELOW<br>AS ABOVE                  |                           |
| NOT LOCATED (2)<br>LPL307 M16 COLLARED EYEBOLT TO BS4278/1<br>LONGSHANK  | 0.80 TONNES<br>AS BELOW<br>AS ABOVE                  |                           |
| NONE   | AS ABOVE   |                           |

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough