

### WHT TCS Cabinet 3 Spares:

	Description:	Note:
1	G4V60(MS)	Cass TT gearbox 
2	FC12TR	Cass TT tacho generator
2	G12M4T-343	NS rotator or Focus Drive motor 
1	F12M2	Cass rotator Motor
1	F12M2A+FC12TR+F12M2	Motor+Tacho+Brake Complete Assembly 
1	14.116.12.1=24V/28W	Brake for AZ/Alt motor
1	6017-22	Bearing
1	MC24PR0533	Cass wrap motor
1	T-10093-A	AZ/Alt motor Kollmorgen repaired by AES 
1	TC5745A	Rotor + Stator tacho generator
2	TC-5723D	Rotor + Stator tacho generator
1	TC-5723D	Stator tacho generator
2	8661107E00 - 05003483	Brake
2bot	ISO-VG220	Oil for gearboxes
5	Keeper rings	For AZ/Alt motors

42 49	A-4477 Brushes A-25383 Caps	For AZ/Alt motors	
1	Squared TUB12	AZ zone sense switch (lever missing)	
4	Omron D4B-1116N	Nasmyth platform detect switch	
1	Reiter P.30.018	Nasmyth gate switch	
4	Honeywell 6LS1-4CRS	Used to detect various position of Alt.	
2	Honeywell BZE7-2RQ9-C	Brake activate switch AZ/Alt	