


INTWFC Cryostat - SDSU Cable

Four cables required, one for each CCD. Lengths t.b.d.



Cable mounting socket
 RS 450-411
 Strain Relief
 RS 450-578

Mixed D socket
 RS 485-029
 Inserts
 RS 485-192 (2 off)
 Use metallised shell.