

Name & Date	Instrument or System	Problem / Maintenance Request
29/5/87 MF/NMP	Shutter Encoders.	No readings from shutter encoders via CAMAC.
1/6/87	CAMAC	<p>Rest crate liked by branch cable  Man O/R buttons on desk tested.  Antibounce card ECT modified to give  stroke to Camac on make and break  of p. ls  Not tested as CAMTST screwed up  the <math>\mu</math>Vax and on Restoring CAMTST  could not be run.</p>
3/6/87	Camac	<p>ECT was on Make only - changed  checked using Camtst - no problems.</p>
8/6/87	Telescope Control	<p>WHT driven in azimuth under MicroVax control.  LR Jones, R Laing, R Wood at 02.00</p>
25/6/87 23.50	Telescope in general	<p>Focus position = 24.66 display units  without mirror support</p>
27/6/87	Telescope control	<p>Driver and tracking under computer control  Control software up and running without previous problems of crashes and corruption of memory. In absence of user interface process, interaction with software, setting and reading of variables etc carried out via GSEXAM: very tedious!</p>