

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 1

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 003 (PL273) 20MM DIA WIRE ROPE SLING 3M SEEE  NONE	4 TON  AS BELOW  AS ABOVE	Y3
LPL 004 (P273) 20MM DIA WIRE ROPE SLING 3M SEEE  NONE	4 TON  AS BELOW  AS ABOVE	Y4
LPL 006 (PL272) 13MM DIA WIRE ROPE SLING 5'0" SEEE  NONE	2 TON  AS BELOW  AS ABOVE	M13
LPL 007 (PL272) 13MM DIA WIRE ROPE SLING 5'0" SEEE  NONE	2 TON  AS BELOW  AS ABOVE	M14
LPL 022 (10/1358) 1" DIA WIRE ROPE SLING 11" TEE  NONE	6 TON  AS BELOW  AS ABOVE	10/13958/ WQ130
LPL 023 (3W2266) 22MM WIRE ROPE SLING 25' TEE  /  KINKED BUT SERVICEABLE	4 TON  AS BELOW  AS ABOVE	10/ 3W2266
LPL 091 (CB/204161) WIRE ROPE SLING 11M EWL  KINKED BUT SERVICEABLE	5.74 TON  AS BELOW  AS ABOVE	NS1726
LPL 092 (CB/204161) WIRE ROPE SLING 11M EWL  NONE	5.74 TON  AS BELOW  AS ABOVE	NS1727

I certify that on 25/09/00 - 02/10/00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature.....



Qualification.....

ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 2

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE  RED
LPL 094 (CB/204002) WIRE ROPE SLING 4.5M EWL	5 TON AS BELOW AS ABOVE	CO6
NONE LPL 098 (3941) 12MM DIA WIRE ROPE SLING 15" TEE	1.44 TONNE AS BELOW AS ABOVE	NS1538
NONE LPL 099 12MM DIA WIRE ROPE SLING 15" TEE	1.44 TONNE AS BELOW AS ABOVE	NS1538
NONE LPL 145 LIFTING BRACKET	15 TONNE AS BELOW AS ABOVE	LW59795
NONE LPL 146 LIFTING BRACKET	15 TONNE AS BELOW AS ABOVE	LW60637
NONE LPL 147 LIFTING BRACKET	15 TONNE AS BELOW AS ABOVE	LW60637
NONE LPL 148 LIFTING BRACKET	15 TONNE AS BELOW AS ABOVE	LW60637
NOT LOCATED (2) LPL 149 LIFTING BRACKET	15 TONNE AS BELOW AS ABOVE	LW60637
NOT LOCATED (2)	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 3

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE  RED
LPL 152 (17033) WIRE ROPE 0.95M  NONE	5.14 TONNE AS BELOW AS ABOVE	3/0308A OO153.83
LPL 153 (17034) WIRE ROPE 0.95M 15" TEE	5.14 TONNE AS BELOW AS ABOVE	3/0308A OO153.83
LPL 154 (17035) WIRE ROPE 0.95M  NONE	5.14 TONNE AS BELOW AS ABOVE	3/0308A OO153.83
LPL 160 (17041) WIRE ROPE 8.79M  NONE	13.1 TONNE AS BELOW AS ABOVE	16/00152
LPL 161 (17042) WIRE ROPE 8.79M  NONE	13.1 TONNE AS BELOW AS ABOVE	16/00152
LPL 162 (17043) WIRE ROPE 8.79M  NONE	13.1 TONNE AS BELOW AS ABOVE	16/00152
LPL 164 (17045) WIRE ROPE 1.73M  NONE	10.06 TONNE AS BELOW AS ABOVE	5/1897
LPL 165 (17046) WIRE ROPE 1.73M  NONE	10.06 TONNE AS BELOW AS ABOVE	5/1897
NOT LOCATED ( 2 )	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature.....



Qualification.....

ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS4

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 166 (17047) WIRE ROPE 1.73M  NONE	10.06 TONNE AS BELOW AS ABOVE	5/1879
LPL 167 (17048) WIRE ROPE 1.73M  NONE	10.06 TONNE AS BELOW AS ABOVE	5/1897
LPL 172 (34011) 1.5/8" SMALL DEE SHACKLE TO BS3032  NONE	13 TON AS BELOW AS ABOVE	29392
LPL 173 (34013) 1.5/8" SMALL DEE SHACKLE TO BS3032  NONE	13 TON AS BELOW AS ABOVE	29392
LPL 174 (34013) 1.5/8" SMALL DEE SHACKLE TO BS3032  NONE	13 TON AS BELOW AS ABOVE	29392
LPL 175 (34014) 1.5/8" SMALL DEE SHACKLE TO BS3032  NONE	13 TON AS BELOW AS ABOVE	29392
LPL 186 (34023) 1.1/2" SMALL DEE SHACKLE TO BS3032  NONE	10.3/4 TON AS BELOW AS ABOVE	27924
LPL 187 (34024) 1.1/2" SMALL DEE SHACKLE  NONE	10.3/4 TON AS BELOW AS ABOVE	27924

I certify that on 25.09.00 - 02.10.00  
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 5

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE	
LPL 190 (34027)	1.1/2" SMALL DEE SHACKLE TO BS3032	10.3/4 TON AS BELOW	RED 27924
NONE		AS ABOVE	
LPL 191 (34028)	1.1/2" SMALL DEE SHACKLE TO BS3032	10.3/4 TON AS BELOW	27924
NONE		AS ABOVE	
LPL 192 (34029)	1.1/2" SMALL DEE SHACKLE TO BS3032	10.3/4 TON AS BELOW	27924
NONE		AS ABOVE	
LPL 193 (34030)	1.1/2" SMALL DEE SHACKLE TO BS3032	10.3/4 TON AS BELOW	27924
NONE		AS ABOVE	
LPL 194 (59087)	1.1/2" SMALL DEE SHACKLE TO BS3032	10.3/4 TON AS BELOW	27924
NONE		AS ABOVE	
NOT LOCATED ( 2 )		AS ABOVE	
LPL 200	LIFTING BRACKET	20 TONNE AS BELOW	62650
NONE		AS ABOVE	
LPL 201	LIFTING BRACKET	20 TONNE AS BELOW	
NONE		AS ABOVE	
LPL 202	LIFTING BRACKET	2 TONNE AS BELOW	59773
NONE		AS ABOVE	

I certify that on 15.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPELDRE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 6

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 203 LIFTING BRACKET	2 TONNE AS BELOW AS ABOVE	RED 59773
NONE LPL 205 LIFTING BRACKET	2 TONNE AS BELOW AS ABOVE	59773
NONE LPL 206 - 41943 LIFTING BRACKET	5 TONNE AS BELOW AS ABOVE	62612
NONE LPL 207 - 41944 LIFTING BRACKET	5 TONNE AS BELOW AS ABOVE	62612
NONE LPL 208 - 41945 LIFTING BRACKET	5 TONNE AS BELOW AS ABOVE	62612
NONE LPL 209 - 41946 LIFTING BRACKET	5 TONNE AS BELOW AS ABOVE	62612
NONE LPL 214 - 41925 LIFTING BRACKET	3 TONNE AS BELOW AS ABOVE	62651
NOT LOCATED (1) LPL 215 - 41926 LIFTING BRACKET	3 TONNE AS BELOW AS ABOVE	62651
NOT LOCATED (1)	AS ABOVE	

I certify that on 25.09.00 - 02.10.00  
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 7

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 216 LIFTING BRACKET  NONE	6 TONNE AS BELOW AS ABOVE	62161
LPL 222 (58675) M20 COLLARED EYEBOLT STORES  NONE	1.25 TONNE AS BELOW AS ABOVE	27471/ 97/270
LPL 223 (A4) M20 COLLARED EYEBOLT STORES  NONE	1.25 TONNE AS BELOW AS ABOVE	27471/ 97/270
LPL 224 M20 COLLARED EYEBOLT STORES  NONE	1.25 TONNE AS BELOW AS ABOVE	27471
LPL 225 M20 COLLARED EYEBOLT STORES  NONE	1.25 TONNE AS BELOW AS ABOVE	LBT13315
LPL 350 (K/274/3A) 13MM DIA WIRE ROPE SLING SEEE  NONE	2 TONNE AS BELOW AS ABOVE	8439
LPL 351 (K/274/3B) 13MM DIA WIRE ROPE SLING SEEE  NONE	2 TONNE AS BELOW AS ABOVE	8439
LPL 352 (K/274/3D) 13MM DIA WIRE ROPE SLING SEEE  NONE	2 TONNE AS BELOW AS ABOVE	8439

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

ENGINEER SUPERVISOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 8

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 353 (K/274/3C) 13MM DIA WIRE ROPE SLING SEEE	2 TONNE AS BELOW	RED 8439
NONE	AS ABOVE	
LPL 531 VERLINDE COMBINED CHAIN HOIST AND TROLLEY	1000 KGS AS BELOW	
WHEEL BEARINGS ON TROLLEY REQUIRE ATTENTION	AS ABOVE	
LPL 532 VERLINDE COMBINED CHAIN HOIST AND TROLLEY	1000 KGS AS BELOW	
WHEEL BEARINGS ON TROLLEY REQUIRE ATTENTION	AS ABOVE	
WN57B LPL696 M52 COLLARED EYEBOLT	10 TONNE AS BELOW	
NONE	AS ABOVE	
5S6371 LPL687 8MM WIRE ROPE SLING 18" EWL SEEE	0.76 TONNE AS BELOW	TEST CERTI- FICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	
5S6571 LPL688 8MM WIRE ROPE SLING 18" EWL SEEE	0.76 TONNE AS BELOW	TEST CERTI- FICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	
16000/31 LPL689 8MM WIRE ROPE SLING 11" EWL SEEE	0.76 TONNE AS BELOW	TEST CERTI- FICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	
16000/32 LPL690 8MM WIRE ROPE SLING 11" EWL SEEE	0.76 TONNE AS BELOW	TEST CERTI- FICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 9

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE  RED
16000/33 LPL691  NONE	8MM WIRE ROPE SLING 11" EWL SEEE  AS BELOW AS ABOVE	0.76 TONNE  TEST CERTIFICATE SHOULD BE HELD ON FILE
16000/34 LPL692  NONE	8MM WIRE ROPE SLING 11" EWL SEEE  AS BELOW AS ABOVE	0.76 TONNE  TEST CERTIFICATE SHOULD BE HELD ON FILE
5T8194 LPL693  NONE	8MM DIA WIRE ROPE SLING 11" EWL SEEE  AS BELOW AS ABOVE	0.76 TONNE  TEST CERTIFICATE SHOULD BE HELD ON FILE
5T8428 LPL694  NONE	8MM DIA WIRE ROPE SLING 11" EWL SEEE  AS BELOW AS ABOVE	0.76 TONNE  TEST CERTIFICATE SHOULD BE HELD ON FILE
LPL682 46000  NONE	5/8" HT RING  AS BELOW AS ABOVE	14 CWT  TEST CERTIFICATE SHOULD BE HELD ON FILE
LPL683 46001  NONE	5/8" HT RING  AS BELOW AS ABOVE	14 CWT  TEST CERTIFICATE SHOULD BE HELD ON FILE
LPL185 34032  NONE	H.T. LARGE DEE SHACKLE TO BS3032  AS BELOW AS ABOVE	35 TON  TEST CERTIFICATE SHOULD BE HELD ON FILE
LPL184 DB789  NONE	H.T. LARGE DEE SHACKLE TO BS3032  AS BELOW AS ABOVE	35 TON  TEST CERTIFICATE SHOULD BE HELD ON FILE

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 10

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE  RED
LPL 139 (41933) LIFTING ROD	19 TONNE AS BELOW	LW62655
NOT LOCATED (2) LPL 140 (41934) LIFTING ROD	AS ABOVE 19 TONNE AS BELOW	LW2656
NOT LOCATED (2) LPL 141 (41927) LIFTING ROD	AS ABOVE 19 TONNE AS BELOW	LW2653
NOT LOCATED (2) LPL 142 (41928) LIFTING ROD	AS ABOVE 19 TONNE AS BELOW	LW2654
NOT LOCATED (2) LPL 272 (LB105) LIFTING FRAME ASSEMBLY (COOLER)	AS ABOVE 1300 KGS AS BELOW	LW70354
NONE LPL 265 (LB96) BEAM 100	AS ABOVE 100 KGS AS BELOW	LW63082
NONE LPL 901 (6046) 7/8" DIA RIGGING SCREW EYE AND JAW	AS ABOVE 22 CWT AS BELOW	M93442/ 97
NONE LPL 902 (6046) 7/8" DIA RIGGING SCREW EYE AND JAW	AS ABOVE 22 CWT	M93442/ 97
NONE		

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 11

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE  RED
LPL 903 (6046)  NONE	7/8" DIA RIGGING SCREW EYE AND JAW  AS BELOW AS ABOVE	M93442/97
LPL 904 (6046)  NONE	7/8" DIA RIGGING SCREW EYE AND JAW  AS BELOW AS ABOVE	M93442/97
LPL 323 (6046)  NONE	7/8" DIA RIGGING SCREW EYE AND JAW  AS BELOW AS ABOVE	M93442/97
NOT LOCATED ( 3 ) LPL 324 (6046)	7/8" DIA RIGGING SCREW EYE AND JAW  AS BELOW AS ABOVE	M93442/97
NOT LOCATED ( 3 ) NO ID NUMBER	RAMSHORN HOOK  AS BELOW AS ABOVE	LW70354
LPL906 LW63077  NONE	LIFTING BRACKET  AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
LPL 907 LW63076  NONE	LIFTING BRACKET  AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
LPL 908 LW63075  NONE	LIFTING BRACKET  AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA GARAGE STORES GS 12

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE  RED
LPL 144 LIFTING BRACKET	15 TON AS BELOW AS ABOVE	
NONE LPL 150 LIFTING BRACKET	15 TON AS BELOW AS ABOVE	
NONE LPL 151 LIFTING BRACKET	15 TON AS BELOW AS ABOVE	
NONE LPL 158 LIFTING BRACKET	15 TON AS BELOW AS ABOVE	
NONE LPL 909 LIFTING BRACKET	500KG AS BELOW AS ABOVE	TEST CERTIFICATE SHOULD BE HELD ON FILE
V21252 VERLINDE TROLLEY	1 TONNE AS BELOW AS ABOVE	
NONE V2152/1 VERLINDE TROLLEY	1 TONNE AS BELOW AS ABOVE	
NONE V2152/2 VERLINDE TROLLEY	1 TONNE AS BELOW AS ABOVE	
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

# EUROLIFTING

GRIFFIN FARM, APPLEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA GARAGE STORES GS 13

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
V21252/3 VERLINDE TROLLEY	1 TONNE AS BELOW AS ABOVE	
NONE V21252/4 VERLINDE TROLLEY	1 TONNE AS BELOW AS ABOVE	
NONE LPL 534 7MM 2 LEG CHAIN SLING	1 TON AS BELOW AS ABOVE	
NONE LPL 265 GANTRY FRAME	1 TON AS BELOW AS ABOVE	
NONE LPL 817 3/4" RIGGING SCREW	22 CWT AS BELOW AS ABOVE	
WHT LPL 818 3/4" RIGGING SCREW	22 CWT AS BELOW AS ABOVE	
NONE		

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough