

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 1

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 027 (88A12) 3/8" LARGE BOW SHACKLE TO BS3032	9 CWT AS BELOW	RED 57976/ 97/1
NOT LOCATED (3)	AS ABOVE	
LPL 035 (CL526) 7/8" LARGE BOW SHACKLE TO BS3032	2.75 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 036 (CL526) 7/8" LARGE BOW SHACKLE TO BS3032	2.75 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 041 (DB288) 1.1/8" LARGE BOW SHACKLE TO BS3032	4.3/4 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 043 (B197) 3/8" LARGE DEE SHACKLE TO BS3032	10 CWT AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 044 (B197) 3/8" LARGE DEE SHACKLE TO BS3032	10 CWT AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 045 (B197) 3/8" LARGE DEE SHACKLE TO BS3032	10 CWT AS BELOW	57976/ 97/1
NOT LOCATED (5)	AS ABOVE	
LPL 046 (DA765) 3/4" LARGE DEE SHACKLE TO BS3032	2 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature.....



Qualification.....

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 2

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 047 (DA765) 3/4" LARGE DEE SHACKLE TO BS3032	2 TON AS BELOW	RED 57976/ 97/1
NOT LOCATED (4)	AS ABOVE	
LPL 048 (DA765) 3/4" LARGE DEE SHACKLE TO BS3032	2 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 049 (DA765) 3/4" LARGE DEE SHACKLE TO BS3032	2 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 050 (CC419) 1" LARGE DEE SHACKLE TO BS3032	3.3/4 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 051 (CC419) 1" LARGE DEE SHACKLE TO BS3032	3.3/4 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 052 (CC419) 1" LARGE DEE SHACKLE TO BS3032	3.3/4 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 054 (DA274) 1.1/8" LARGE DEE SHACKLE TO BS3032	5 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	
LPL 055 (DA274) 1.1/8" LARGE DEE SHACKLE TO BS3032	5 TON AS BELOW	57976/ 97/1
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 3

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 056 (DA274) 1.1/8" LARGE DEE SHACKLE TO BS3032	5 TON AS BELOW AS ABOVE	RED 57976/ 97/1
NONE LPL 057 (DA274) 1.1/8" LARGE DEE SHACKLE TO BS3032	5 TON AS BELOW AS ABOVE	57976/ 97/1
NONE LPL 059 (TF4763) 7/8" INT DEE SHACKLE	6.5 TONNE AS BELOW AS ABOVE	57976/ 97/2
NOT LOCATED (1) LPL 062 (E231) M12 COLLARED EYEBOLT	320 KGS AS BELOW AS ABOVE	57976/ 97/2
NOT LOCATED (3) LPL 064 (F260) M12 COLLARED EYEBOLT	320 KGS AS BELOW AS ABOVE	57976/ 97/2
NOT LOCATED (3) LPL 065 (380) M12 COLLARED EYEBOLT	320 KGS AS BELOW AS ABOVE	57976/ 97/2
NOT LOCATED (3) LPL 067 (374) M12 COLLARED EYEBOLT	0.32 TONNE AS BELOW AS ABOVE	57976/ 97/2
NOT LOCATED (3) LPL 068 (A3) M18 COLLARED EYEBOLT	1 TONNE AS BELOW AS ABOVE	57976/ 97/2
NOT LOCATED (4)	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature.....



Qualification.....

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 4

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 074 (A5) M22 COLLARED EYEBOLT	1.60 TONNE AS BELOW	RED 57976/ 97/2
NONE LPL 077 M22 COLLARED EYEBOLT	AS ABOVE 1.60 TONNE AS BELOW	57976/ 97/2
NONE LPL 079 (A5) M22 COLLARED EYEBOLT	AS ABOVE 1.6 TONNE AS BELOW	57976/ 97/2
NONE LPL 080 (A6) M24 COLLARED EYEBOLT	AS ABOVE 2 TONNE AS BELOW	57976/ 97/2
NONE LPL 081 M24 COLLARED EYEBOLT	AS ABOVE 2 TONNE AS BELOW	57976/ 97/2
NONE LPL 084 (A6) M24 COLLARED EYEBOLT	AS ABOVE 2 TONNE AS BELOW	57976/ 97/2
NONE LPL 085 (A6) M24 COLLARED EYEBOLT	AS ABOVE 2 TONNE AS BELOW	57976/ 97/2
NONE LPL 087 FULL SAFETY HARNESS C/W LANYARD	AS ABOVE N/A AS BELOW	
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that it is safe for use.

Signature 

QUALIFIED

Examined on a thorough

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 5

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 095 (45844) ELEPHANT SUPER 80 CHAIN BLOCK NONE	5 TON AS BELOW AS ABOVE	RED E3516
LPL 096 (58484/97) ELEPHANT SUPER 80 CHAIN BLOCK NONE	2 TON AS BELOW AS ABOVE	E3516
LPL 105 (58484/97) 1.5/8" LARGE DEE SHACKLE TO BS3032 GARAGE NONE	11.1/4 TON AS BELOW AS ABOVE	58484/97
LPL 106 (58584/97) 1.5/8" LARGE DEE SHACKLE TO BS3032 GARAGE NONE	11.1/4 TON AS BELOW AS ABOVE	58484/97
LPL 108 (JW849) 5/8" LARGE BOW SHACKLE TO BS3032 NONE	25 CWT AS BELOW AS ABOVE	100681
LPL 121 (31825) 1.5/8" LARGE DEE SHACKLE TO BS3032 GARAGE NONE	11.1/4 TON AS BELOW AS ABOVE	C868
LPL 122 (31826) 1.5/8" LARGE DEE SHACKLE TO BS3032 NONE	11.1/4 TON AS BELOW AS ABOVE	C704
LPL 176 (34015) 1.1/8" SMALL DEE SHACKLE TO BS3032 NONE	5.1/2 TON AS BELOW AS ABOVE	29394

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

ISAAC NEWTON GROUP OF TELESCOPES

LA PALMA LIFTING TACKLE STORES LTS 6

Address

Distinguishing number and description
Defects and observations

Safe working load
Date of examination
Location

COLOUR
CODE

RED

29394

LPL 177 (34016)

1.1/8" SMALL DEE SHACKLE TO BS3032

5.1/2 TON

AS BELOW

AS ABOVE

NONE

LPL 178 (34017)

1.1/8" SMALL DEE SHACKLE TO BS3032

5.1/2 TON

AS BELOW

AS ABOVE

NONE

LPL 179 (34018)

1.1/8" SMALL DEE SHACKLE TO BS3032

5.1/2 TON

AS BELOW

AS ABOVE

NOT LOCATED (1)

LPL 180 (34019)

1.1/8" SMALL DEE SHACKLE TO BS3032

5.1/2 TON

AS BELOW

AS ABOVE

NONE

LPL 181 (34020)

1.1/8" SMALL DEE SHACKLE TO BS3032

5.1/2 TON

AS BELOW

AS ABOVE

NONE

LPL 182 (34021)

1.1/8" SMALL DEE SHACKLE TO BS3032

5.1/2 TON

AS BELOW

AS ABOVE

NONE

LPL 183 (34022)

1.1/8" SMALL DEE SHACKLE TO BS3032

5.1/2 TON

AS BELOW

AS ABOVE

NONE

LPL 195 (59088)

M36 COLLARED EYEBOLT

5 TONNE

AS BELOW


AS ABOVE

NONE

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 7

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 222 (58675) DUPLICATED NONE	M20 COLLARED EYEBOLT 1.25 TONNE AS BELOW AS ABOVE	RED 27471/ 97/270
LPL 223 (A4) DUPLICATED NONE	M20 COLLARED EYEBOLT 1.25 TONNE AS BELOW AS ABOVE	27471/ 97/270
LPL 224 DUPLICATED NONE	M20 COLLARED EYEBOLT 1.25 TONNE AS BELOW AS ABOVE	27471
LPL 803 (59670) NONE	M36 COLLARED EYEBOLT 5 TONNE AS BELOW AS ABOVE	L200/1
LPL 804 (59672) NONE	M36 COLLARED EYEBOLT 5 TONNE AS BELOW AS ABOVE	L200/2
LPL 801 (59673) NONE	M36 COLLARED EYEBOLT 5 TONNE AS BELOW AS ABOVE	L200/3
LPL 802 (59671) NONE	M36 COLLARED EYEBOLT 5 TONNE AS BELOW AS ABOVE	L200/4
LPL 271 (H3) NOT LOCATED (6)	M12 COLLARED EYEBOLT 320 KGS AS BELOW AS ABOVE	29867

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification..... ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 8

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 273 1/2" SMALL BOW SHACKLE TO BS3032	1 TON AS BELOW	RED 5000/ 599/ 8327
NOT LOCATED (3) LPL 277 8MM 3 LEG WIRE SLING C/W SEEE	AS ABOVE 0.82 TONNE AS BELOW	16T7170
NONE LPL 280 1" WIDE POLYESTER WEB SLING TYPE LM3	AS ABOVE 500 KGS AS BELOW	7622
NOT LOCATED (1) LPL 282 (CS305) 3/8" SMALL BOW SHACKLE TO BS3032	AS ABOVE 10 CWT AS BELOW	29865
NONE LPL 284 (CS309) 1/2" SMALL BOW SHACKLE TO BS3032	AS ABOVE 1 TON AS BELOW	29865
NOT LOCATED (1) LPL 288 8MM 3 LEG WIRE SLING C/W SEEE	AS ABOVE 0.82 TONNE AS BELOW	16/02699
NONE LPL 289 M18 COLLARED EYEBOLT	AS ABOVE 1 TONNE AS BELOW	29865
NOT LOCATED (2) LPL 290 M18 COLLARED EYEBOLT	AS ABOVE 1 TONNE AS BELOW	29865
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 9

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 307 6" WIDE X 2M SIMPLEX WEBBING SLING	3 TONNE AS BELOW AS ABOVE	RED O2174
NONE LPL 308 6" WIDE X 2M SIMPLEX WEBBING SLING	3 TONNE AS BELOW AS ABOVE	O2175
NONE LPL 309 6" WIDE X 2M SIMPLEX WEBBING SLING	3 TONNE AS BELOW AS ABOVE	O2176
NONE LPL 310 6" WIDE X 3M WEBBING SLING	3 TONNE AS BELOW AS ABOVE	O2177
NONE LPL 311 6" WIDE X 3M SIMPLEX WEBBING SLING	3 TONNE AS BELOW AS ABOVE	O2178
NONE LPL 312 6" WIDE X 3M SIMPLEX WEBBING SLING	3 TONNE AS BELOW AS ABOVE	O2179
NONE LPL 313 6" WIDE X 3M SIMPLEX WEBBING SLING	3 TONNE AS BELOW AS ABOVE	O2180
NONE LPL 314 6" WIDE X 5M SIMPLEX WEBBING SLING	3 TONNE AS BELOW AS ABOVE	O2181

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification..... ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 10

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 316 (6723EZ) NONE	T516 TIRFOR WINCH C/W HANDLE 1600 KGS AS BELOW AS ABOVE	RED 417038
LPL316A (HW3170) NONE	T516 TIRFOR WIRE ROPE 20M 32 CWT AS BELOW AS ABOVE	417038
LPL 317 NONE	T508 TIRFOR WINCH 0.8 TONNE AS BELOW AS ABOVE	31090
LPL 317A (85343) NONE	T508 TIRFOR WIRE ROPE 20M 0.8 TONNE AS BELOW AS ABOVE	417039
LPL 318 (0248EX) NONE	T508 TIRFOR WINCH C/W HANDLE 0.8 TONNE AS BELOW AS ABOVE	417040
LPL 318A (85/90) NONE	T508 TIRFOR WIRE ROPE 2M 0.8 TONNE AS BELOW AS ABOVE	417040
LPL 330 (49939) NONE	TL10 POLYESTER ROUND SLING 1 TONNE AS BELOW AS ABOVE	31090
LPL 336 (14911) NOT LOCATED (1)	2" X 2M WEBBING SLING 1 TONNE AS BELOW AS ABOVE	

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature:  Qualification: ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 11

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
		RED
LPL 343 2" WIDE X 2M WEBBING SLING	1 TONNE AS BELOW	
NOT LOCATED (1)	AS ABOVE	
LPL 345 2" WIDE X 2M WEBBING SLING	1 TONNE AS BELOW	14995
	AS ABOVE	
NONE		
LPL 355 (184/1) ALLOY STEEL DEE SHACKLE TO US SPEC	1 TON AS BELOW	55909/ 24/86
	AS ABOVE	
NONE		
LPL 356 (184/1) ALLOY STEEL DEE SHACKLE TO US SPEC	1 TON AS BELOW	55909/ 24/86
	AS ABOVE	
NONE		
LPL 357 (184/1) ALLOY STEEL DEE SHACKLE TO US SPEC	1 TON AS BELOW	55909/ 24/86
	AS ABOVE	
NONE		
LPL 358 (184/1) ALLOY STEEL DEE SHACKLE TO US SPEC	1 TON AS BELOW	55909/ 24/86
	AS ABOVE	
NOT LOCATED (3)		
LPL 359 (184/1) ALLOY STEEL DEE SHACKLE TO US SPEC	1 TON AS BELOW	55909/ 24/86
	AS ABOVE	
NONE		
LPL 360 (184/1) ALLOY STEEL DEE SHACKLE TO US SPEC	1 TON AS BELOW	55909/ 24/86
	AS ABOVE	
NONE		

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 12

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 371 (184/3) ALLOY STEEL DEE SHACKLE TO US SPEC	3.1/4 TON AS BELOW AS ABOVE	RED 55909/ 24/86
NONE LPL 372 (184/3) ALLOY STEEL DEE SHACKLE TO US SPEC	3.1/4 TON AS BELOW AS ABOVE	55909/ 24/86
NONE LPL 373 (184/3) ALLOY STEEL DEE SHACKLE TO US SPEC	3.1/4 TON AS BELOW AS ABOVE	55909/ 24/86
NONE LPL 378 (A1) M12 COLLARED EYEBOLT	0.4 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (5) LPL 379 (A1) M12 COLLARED EYEBOLT	0.4 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (3) LPL 380 (A1) M12 COLLARED EYEBOLT	0.4 TONNE AS BELOW AS ABOVE	55909/ 24/86
NONE LPL 381 (A1) M12 COLLARED EYEBOLT	0.4 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (7) LPL 385 (A2) M16 COLLARED EYEBOLT	0.8 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (2)	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 13

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL663 - A4 M20 COLLARED EYEBOLT	1.25 TONNE AS BELOW AS ABOVE	
NONE LPL664 - A4 M20 COLLARED EYEBOLT	1.25 TONNE AS BELOW AS ABOVE	
NONE LPL665 - A4 M20 COLLARED EYEBOLT	1.25 TONNE AS BELOW AS ABOVE	
NONE LPL666 - A4 M20 COLLARED EYEBOLT	1.25 TONNE AS BELOW AS ABOVE	
NONE		

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 14

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 386 (A2) M16 COLLARED EYEBOLT	0.8 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (2) LPL 388 (A2) M16 COLLARED EYEBOLT	0.8 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (2) LPL 389 (A2) M16 COLLARED EYEBOLT	0.8 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (2) LPL 390 (A4) M20 COLLARED EYEBOLT	1.6 TONNE AS BELOW AS ABOVE	55909/ 24/86
NONE LPL 391 (A4) M20 COLLARED EYEBOLT	1.6 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (1) LPL 392 (A4) M20 COLLARED EYEBOLT	1.6 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (1) LPL 393 (A4) M20 COLLARED EYEBOLT	1.6 TONNE AS BELOW AS ABOVE	55909/ 24/86
NOT LOCATED (4) LPL 398 (A6) M24 COLLARED EYEBOLT	2.5 TONNE AS BELOW AS ABOVE	55909/ 24/86
NONE		

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification..... ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552


REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 15

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 399 (A6) M24 COLLARED EYEBOLT	2.5 TONNE AS BELOW AS ABOVE	RED 55909/ 24/86
NOT LOCATED (1) LPL 404 (15043) 1 MT CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW AS ABOVE	15048
NOT LOCATED (3) LPL 405 (15048) 1 MT CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW AS ABOVE	15048
NONE LPL 406 (15048) 1 MT CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW AS ABOVE	15048
NONE LPL 407 (15048) 1MT CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW AS ABOVE	15048
NOT LOCATED (2) LPL 421 (C33912) 4 MT CIRC POLYESTER ROUNDSLING F/W WEAR SLEEVES	20 TONNE AS BELOW AS ABOVE	48186
NONE LPL 424 (31080) 7 MT CIRC POLYESTER ROUNDSLING	3 TONNE AS BELOW AS ABOVE	46896
NOT LOCATED (3) LPL 430 HT LARGE BOW SHACKLE TO BS3032	2 TON AS BELOW AS ABOVE	170/ 2503/F97
NOT LOCATED (5)	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature



Qualification

ENGINEER SURVEYOR