

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 16

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 431 HT LARGE BOW SHACKLE TO BS3032	2 TON AS BELOW	RED 170/ 2530/F97
NOT LOCATED (4) LPL 432 HT LARGE BOW SHACKLE TO BS3032	AS ABOVE 2 TON AS BELOW	170/ 2530/F97
NOT LOCATED (5) LPL 446 (PE6507) MORRIS 127 LITALIFT HAND CHAIN HOIST	AS ABOVE 0.5 TONNE AS BELOW	HC202
NONE LPL 447 (R275) BEAM CLAMP	AS ABOVE 0.5 TONNE AS BELOW	HC205
NONE LPL 453 (7111495/200) FELCO MB80 ELECTRIC CHAIN HOIST C/W 20'0" HOL	AS ABOVE 250 KGS AS BELOW	HC191
NOT TO BE USED UNTIL TESTED LPL 454 (7111496/201) FELCO MB80 ELECTRIC CHAIN HOIST	AS ABOVE 250 KGS AS BELOW	HC192
NOT TO BE USED UNTIL TESTED LPL 951 (21750) 4M CIRC POLYESTER ROUND SLING	AS ABOVE 3000 KGS AS BELOW	O2038
NOT LOCATED (1) LPL 953 (21751) 4M CIRC POLYESTER ROUND SLING	AS ABOVE 3000 KGS AS BELOW	O2038
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 17

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 458 (21752) 4M CIRC POLYESTER ROUND SLING	3000 KGS AS BELOW	RED O2038
NOT LOCATED (1) LPL 460 (21754) 6M CIRC POLYESTER ROUND SLING	AS ABOVE 3000 KGS AS BELOW	O2038
NOT LOCATED (1) LPL 954 (21755) 6M CIRC POLYESTER ROUND SLING	AS ABOVE 3000 KGS AS BELOW	O2038
NONE LPL 462 (21756) 6M CIRC POLYESTER ROUND SLING	AS ABOVE 3000 KGS AS BELOW	O2038
NONE LPL 463 (21757) 8M CIRC POLYESTER ROUND SLING	AS ABOVE 3000 KGS AS BELOW	O2038
NONE LPL 465 (21759) 12M CIRC POLYESTER ROUND SLING	AS ABOVE 3000 KGS AS BELOW	O2038
NOT LOCATED (1) LPL 467 (9825) TANGYE HYDRA CLAW JACK C/W HANDLE	AS ABOVE 5 TON AS BELOW	CERTIFI- CATE FOUND - NO NUMBER
NONE LPL 468 (9826) TANGYE HYDRA CLAW JACK C/W HANDLE	AS ABOVE 5 TON AS BELOW	CERTIFI- CATE FOUND - NO NUMBER
NONE	AS ABOVE	NUMBER

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the results

Signature 

Qualification

I carried out a thorough

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 18

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 470 (97330) 3M CIRC POLYESTER ROUND SLING	2 TONNE AS BELOW AS ABOVE	RED CERTIFICATE SHOULD BE HELD ON FILE
NONE LPL 473 1" WHIT COLLARED EYEBOLT	2 TONNE AS BELOW AS ABOVE	53462
NONE LPL 474 1" WHIT COLLARED EYEBOLT	2 TONNE AS BELOW AS ABOVE	53462
NONE LPL 475 1" WHIT COLLARED EYEBOLT	2 TONNE AS BELOW AS ABOVE	53462
NONE LPL 476 1" WHIT COLLARED EYEBOLT	2 TONNE AS BELOW AS ABOVE	53462
NONE LPL 477 7/8" WHIT COLLARED EYEBOLT	2 TONNE AS BELOW AS ABOVE	53462
NONE LPL 478 7/8" WHIT COLLARED EYEBOLT	2 TONNE AS BELOW AS ABOVE	53462
NOT LOCATED (3) LPL 479 7/8" WHIT COLLARED EYEBOLT	2 TONNE AS BELOW AS ABOVE	53462
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LT19

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 480 7/8" WHIT COLLARED EYEBOLT	2 TONNE AS BELOW	RED 53462
NONE	AS ABOVE	
LPL 481 3/4" WHIT COLLARED EYEBOLT	1.4 TONNE AS BELOW	53462
NONE	AS ABOVE	
LPL 482 3/4" WHIT COLLARED EYEBOLT	1.4 TONNE AS BELOW	53462
NOT LOCATED (2)	AS ABOVE	
LPL 483 3/4" WHIT COLLARED EYEBOLT	1.4 TONNE AS BELOW	53462
NONE	AS ABOVE	
LPL 484 5/8" WHIT COLLARED EYEBOLT	0.9 TONNE AS BELOW	53462
NONE	AS ABOVE	
LPL 485 5/8" WHIT COLLARED EYEBOLT	0.9 TONNE AS BELOW	53462
NONE	AS ABOVE	
LPL 486 5/8" WHIT COLLARED EYEBOLT	0.9 TONNE AS BELOW	53462
NONE	AS ABOVE	
LPL 487 5/8" WHIT COLLARED EYEBOLT	0.5 TONNE AS BELOW	53462
NOT LOCATED (4)	AS ABOVE	
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature 

Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552


REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 20

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 488 1/2" WHIT COLLARED EYEBOLT	0.5 TONNE AS BELOW	RED 53462
NONE	AS ABOVE	
LPL 489 1/2" WHIT COLLARED EYEBOLT	0.5 TONNE AS BELOW	53462
NOT LOCATED (1)	AS ABOVE	
LPL 490 1/2" WHIT COLLARED EYEBOLT	0.5 TONNE AS BELOW	53462
NOT LOCATED (5)	AS ABOVE	
LPL 493 3/8" WHIT COLLARED EYEBOLT	250 KGS AS BELOW	53462
NOT LOCATED (5)	AS ABOVE	
LPL 494 3/8" WHIT COLLARED EYEBOLT	250 KGS AS BELOW	53462
NOT LOCATED (5)	AS ABOVE	
LPL 495 3/8" WHIT COLLARED EYEBOLT	250 KGS AS BELOW	53462
NOT LOCATED (5)	AS ABOVE	
LPL 497 (012794) 6M CIRC POLYESTER ROUND SLING	2 TONNE AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
NOT LOCATED (1)	AS ABOVE	
LPL 498 M24 COLLARED EYEBOLT	2.5 TONNE AS BELOW	44815
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature 

Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552


REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 21

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE	
LPL 499	5M CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW	RED TEST CERTIFICATE SHOULD BE HELD ON FILE
NONE		AS ABOVE	
LPL 499A	8MM DIA WIRE ROPE SLING C/W SEEE	500 KGS AS BELOW	44815
		AS ABOVE	
NOT LOCATED (6)			
LPL 500	6M CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
		AS ABOVE	
NONE			
LPL 500A	6" WIDE WEBBING SLING	3 TONNE AS BELOW	44815
		AS ABOVE	
NONE			
LPL 501 (025905)	5M CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
		AS ABOVE	
NONE			
LPL 501A	M12 COLLARED EYEBOLT	320 KGS AS BELOW	44815
		AS ABOVE	
NOT LOCATED (4)			
LPL 502	M12 COLLARED EYEBOLT	320 KGS AS BELOW	44815
		AS ABOVE	
NOT LOCATED (4)			
LPL 503	M16 COLLARED EYEBOLT	0.8 TONNE AS BELOW	44815
		AS ABOVE	
NOT LOCATED (2)			

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature



Qualification

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 22

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 504 M16 COLLARED EYEBOLT NONE	0.8 TONNE AS BELOW AS ABOVE	RED 44815
LPL 505 M16 COLLARED EYEBOLT NONE	0.8 TONNE AS BELOW AS ABOVE	44815
LPL 506 3/8" SMALL DEE SHACKLE TO BS3032 NONE	0.8 TONNE AS BELOW AS ABOVE	44815
NOT LOCATED (6) LPL 529 VERLINDE CHAIN HOIST NONE	AS ABOVE 1000 KGS AS BELOW AS ABOVE	
O12794 6M CIRC POLYESTER ROUNDSLING NOT LOCATED (3)	2 TONNE AS BELOW AS ABOVE	TEST CERTIFICATE SHOULD BE HELD ON FILE
LPL 530 VERLINDE CHAIN HOIST NONE	1000 KGS AS BELOW AS ABOVE	
LPL 533 (WL0936) 7MM DIA 4 LEG CHAIN SLING F/W SHORTENING CLUTCHES, LEGS ENDING IN SAFETY SLING HOOKS NONE	2250 KGS AT 60 DEG AS BELOW AS ABOVE	WCT0936
LPL 534 (WL0938) 7MM DIA 2 LEG CHAIN SLING LEGS ENDING IN HT 1.1/2 TON SHACKLES NONE	1000 KGS AT 60 DEG AS BELOW AS ABOVE	WCT0938

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature.....



Qualification.....

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552


REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 23

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
1 X SET DORVIC SHIFTING SKATES C/W TURNTABLES, EQUALISERS, CROSSBARS AND HANDLES	40 TON PER SET OF 4 AS BELOW	RED
NOT LOCATED LPL897 844526	AS ABOVE 2000 KGS	
	IN W.H.T.	AS BELOW
NONE O1685	AS ABOVE 50 TONNE	TEST CERTI- FICATE SHOULD BE HELD ON FILE
HANDLE MISSING, DAMAGE TO SCREW EXTENSION O1686	AS BELOW 30 TONNE	TEST CERTI- FICATE SHOULD BE HELD ON FILE
HANDLE MISSING O1687	AS ABOVE 30 TONNE	TEST CERTI- FICATE SHOULD BE HELD ON FILE
HANDLE MISSING LPL962 30082	AS BELOW SWL N/A	
	AS ABOVE	
NONE 560	AS BELOW SWL 2 TON	
	AS ABOVE	
LPL814	15 TONNE CAPACITY PER SET OF 4 AS BELOW AS ABOVE	
NONE		

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature  Qualification.....

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552


REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 24

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 009 HT STEEL MASTER RING	1.2 TON	RED
NONE	AS ABOVE	
LPL 012 CHOKER "D" WEBBING SLING	1.5 TON	
	AS BELOW	
NOT LOCATED (2)	AS ABOVE	
LPL 019 RATCHET TOE JACK	5 TON	TEST CERTIFICATE SHOULD BE HELD ON FILE
	AS BELOW	
OPERATING HANDLE MISSING	AS ABOVE	
LPL 027 (881A12) 3/8" LARGE BOW SHACKLE TO BS3032	9 CWT	57976/ 97/1
	AS BELOW	
	AS ABOVE	
LPL 028 (882A12) 3/8" LARGE BOW SHACKLE TO BS3032	9 CWT	57976/ 97/1
	AS BELOW	
	AS ABOVE	
LPL 030 (CZ492) 5/8" LARGE BOW SHACKLE TO BS3032	25 CWT	57976/ 97/1
	AS BELOW	
	AS ABOVE	
LPL 032 (CZ592) 5/8" LARGE BOW SHACKLE TO BS3032	25 CWT	57976/ 97/1
	AS BELOW	
	AS ABOVE	
LPL 033 (CZ492) 5/8" LARGE BOW SHACKLE TO BS3032	25 CWT	57976/ 97/1
	AS BELOW	
	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 25

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 034 7/8" LARGE BOW SHACKLE TO BS3032	2.3/4 TON	57976/ 97/1
NONE	AS ABOVE	
LPL 036 7/8" LARGE BOW SHACKLE TO BS3032	2.3/4 TON	57976/ 97/1
NONE	AS BELOW	
NONE DUPLICATED	AS ABOVE	
LPL 037 (CL526) 7/8" LARGE BOW SHACKLE TO BS3032	2.3/4 TON	57976/ 97/1
NONE	AS BELOW	
LPL 038 (DB288) 1.1/8" LARGE BOW SHACKLE TO BS3032	4.3/4 TON	57976/ 97/1
NONE	AS BELOW	
LPL 040 (DB288) 1.1/8" LARGE BOW SHACKLE TO BS3032	4.3/4 TON	57976/ 97/1
NONE	AS BELOW	
LPL 060 (TG101082) 1" INT DEE SHACKLE	8.5 TON	57977/97
NONE	AS BELOW	
LPL 061 (TG101082) 1" INT DEE SHACKLE	8.5 TON	57977/97
NONE	AS BELOW	
LPL 507 3/8" LARGE DEE SHACKLE TO BS3032	10 CWT	44815
NOT LOCATED (4)	AS BELOW	
	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552


REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 26

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 508 3/8" WHIT COLLARED EYEBOLT	5 CWT AS BELOW	RED 44815
NOT LOCATED (5)	AS ABOVE	
LPL 509 ALLOY STEEL DEE SHACKLE	3.25 TON AS BELOW	44815
NONE	AS ABOVE	
LPL 511 5M CIRC POLYESTER ROUNDSLING	2 TON AS BELOW	44815
NOT LOCATED (5)	AS ABOVE	
LPL 512 2" WIDE X 4M CIRC ENDLESS FLAT SLING	2 TONNE AS BELOW	44944
NONE	AS ABOVE	
LPL 513 2" WIDE X 4M 3 LEG WEBBING SLING	2 TONNE AS BELOW	44944
NOT LOCATED (1)	AS ABOVE	
LPL 514 M12 COLLARED EYEBOLT	0.4 TONNE AS BELOW	44944
NOT LOCTED (4)	AS ABOVE	
LPL 515 M12 LONGSHANK COLLARED EYEBOLT	0.4 TONNE AS BELOW	44944
NOT LOCATED (3)	AS ABOVE	
LPL 516 M12 LONGSHANK COLLARED EYEBOLT	0.4 TONNE AS BELOW	44944
NOT LOCATED (3)	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address


LA PALMA LIFTING TACKLE STORES LTS 27

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 535A	TIRFOR DYNAFOR LOAD LINK	RED
	5 TONNE CAPACITY	
	AS BELOW	
OUT OF TEST	AS ABOVE	
LPL 550	12M CIRC POLYESTER ROUNDSLING	3233
	3 TONNE	
	AS BELOW	
NONE	AS ABOVE	
LPL 551	12M CIRC POLYESTER ROUNDSLING	3233
	3 TONNE	
	AS BELOW	
NONE	AS ABOVE	
LPL 552	12M CIRC POLYESTER ROUNDSLING	3233
	3 TONNE	
	AS BELOW	
NONE	AS ABOVE	
LPL 553	12M CIRC POLYESTER ROUNDSLING	3233
	3 TONNE	
	AS BELOW	
NONE	AS ABOVE	
LPL 554	12M CIRC POLYESTER ROUNDSLING	50488
	3 TONNE	
	AS BELOW	
NONE	AS ABOVE	
LPL 555	8M CIRC POLYESTER ROUNDSLING	3233
	3 TONNE	
	AS BELOW	
NONE	AS ABOVE	
LPL 556	8M CIRC POLYESTER ROUNDSLING	3233
	3 TONNE	
	AS BELOW	
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier
Address

ISAAC NEWTON GROUP OF TELESCOPES
LA PALMA LIFTING TACKLE STORES LTS 28

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 557 8M CIRC POLYESTER ROUNDSLING	3 TONNE AS BELOW AS ABOVE	3233
NOT LOCATED (1) LPL 558 6M CIRC POLYESTER ROUNDSLING	3 TONNE AS BELOW AS ABOVE	3233
NONE LPL 559 6M CIRC POLYESTER ROUNDSLING	3 TONNE AS BELOW AS ABOVE	3233
NOT LOCATED (2) LPL 560 6M CIRC POLYESTER ROUNDSLING	3 TONNE AS BELOW AS ABOVE	3233
NONE LPL 561 6M CIRC POLYESTER ROUNDSLING	3 TONNE AS BELOW AS ABOVE	3233
NONE LPL 562 SPREADER BEAM (675 HOLE CENTRES)	300 KGS AS BELOW AS ABOVE	50488
NONE LPL 563 2M CIRC POLYESTER ROUNDSLING	1 TONNE AS BELOW AS ABOVE	3233
NONE LPL 564 2M CIRC POLYESTER ROUNDSLING	1 TONNE AS BELOW AS ABOVE	3233
NONE		

I certify that on 25.09.00 - 02.10.00
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature  Qualification..... ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 29

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 565	2M CIRC POLYESTER ROUND SLING	RED 3233
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 566	2M CIRC POLYESTER ROUND SLING	3233
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 567	2M CIRC POLYESTER ROUND SLING	3233
NOT LOCATED (3)	AS BELOW	
NONE	AS ABOVE	
LPL 568	2M CIRC POLYESTER ROUND SLING	3233
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 569	2M CIRC POLYESTER ROUND SLING	3233
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 570	2M CIRC POLYESTER ROUND SLING	3233
NOT LOCATED (2)	AS BELOW	
NONE	AS ABOVE	
LPL 571	2M CIRC POLYESTER ROUND SLING	3233
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 572	2M CIRC POLYESTER ROUND SLING	3233
NONE	AS BELOW	
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address


LA PALMA LIFTING TACKLE STORES LTS 30

Distinguishing number and description Defects and observations		Safe working load Date of examination Location	COLOUR CODE
LPL 573	2M CIRC POLYESTER ROUND SLING	1 TONNE AS BELOW AS ABOVE	RED 3233
NOT LOCATED (2) LPL 574	2M CIRC POLYESTER ROUND SLING	1 TONNE AS BELOW AS ABOVE	3233
NONE EPL288 RG 3417	3 LEG WIRE ROPE SLING	3 TONNE AS BELOW AS ABOVE	
DUPLICATED			
NONE 15742	6M CIRC POLYESTER ROUND SLING	3 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NOT LOCATED (2) 14800	6M CIRC POLYESTER ROUND SLING	3 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NONE 14808	6M CIRC POLYESTER ROUND SLING	3 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NONE 0012	2M CIRC POLYESTER ROUND SLING	1 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NOT LOCATED (4) 0085	2M CIRC POLYESTER ROUND SLING	1 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NOT LOCATED (4)			

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR