

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 1

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 020 (8771059) GENIE SUPER LIFT SL18	650 KGS AS BELOW AS ABOVE	RED 60416
NONE LPL 025 (9051328) CLIMA LIFT MOBILE	225 KGS AS BELOW AS ABOVE	889
MAIN LEAD SHOULD HAVE AN INDUSTRIAL PLUG, NOT R.C.D. TYPE LPL 887 PSL226 GENIE PSLA-20 BATTERY POWERED	650 KGS AS BELOW AS ABOVE	57976/97/1
NONE LPL 100 WHARTON E.O.T CRANE	25 TON AS BELOW AS ABOVE	8526 09.10.00
NONE LOAD TESTED 30.09.00 LPL 102 WHARTON BOTTOM BLOCK ASSEMBLY	25 TON AS BELOW AS ABOVE	18029
NONE LPL 108 (JW849) 5/8" LARGE BOW SHACKLE TO BS3032	25 CWT AS BELOW AS ABOVE	100681
DUPLICATED LPL 109 (JW849) 5/8" LARGE BOW SHACKLE TO BS3032	25 CWT AS BELOW AS ABOVE	100681
NONE LPL 110 (JW849) 5/8" LARGE BOW SHACKLE TO BS3032	25 CWT AS BELOW AS ABOVE	100681
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES


Address

LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 2

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE RED
LPL 130 (LB95) LIFTING BEAM	45 TONNE AS BELOW	LW62648
NOT LOCATED	AS ABOVE	
LPL 131 LIFTING PIN	22.50 TONNE AS BELOW	LW2661
NOT LOCATED	AS ABOVE	
LPL 132 LIFTING PIN	22.50 TONNE AS BELOW	LW2661
NOT LOCATED	AS ABOVE	
LPL 133 LIFTING PIN	22.50 TONNE AS BELOW	LW2661
NOT LOCATED	AS ABOVE	
LPL 134 LIFTING PIN	22.50 TONNE AS BELOW	LW2661
NOT LOCATED	AS ABOVE	
LPL 151 (17032) WIRE ROPE 0.95M GARAGE STORE	5.14 TONNE AS BELOW	3/0308A001 53.83
NONE	AS ABOVE	
LPL 163 (17044) WIRE ROPE 8.79MT	13.1 TONNE AS BELOW	16/00152
NONE	AS ABOVE	
LPL 168 LIFTING BRACKET	10 TON AS BELOW	42298
NONE	AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature: 

Qualification: ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier
Address

ISAAC NEWTON GROUP OF TELESCOPES
LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 3

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 169 LIFTING BRACKET NONE	10 TON AS BELOW AS ABOVE	42299
LPL 170 LIFTING BRACKET NONE	10 TON AS BELOW AS ABOVE	42299
LPL 171 LIFTING BRACKET NONE	13 TON AS BELOW AS ABOVE	42301
LPL365 1/2" X 5/8" ALLOY STEEL DEE SHACKLE TO US FEDERAL SPEC RR-C-271B NONE	2 TON AS BELOW AS ABOVE	
LPL366 1/2" X 5/8" ALLOY STEEL DEE SHACKLE TO US FEDERAL SPEC RR-C-271B NONE	2 TON AS BELOW AS ABOVE	
NOT LOCATED (1) LPL 196 LIFTING BRACKET	10 TONNE AS BELOW AS ABOVE	61114
LPL 197 LIFTING BRACKET NONE	10 TONNE AS BELOW AS ABOVE	61114
LPL 198 LIFTING BRACKET NONE	10 TONNE AS BELOW AS ABOVE	61114

I certify that on 25.09.00 - 02.10.00
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

ENGINEER SUPERVISOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 4

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE	
		RED	
LPL 199	LIFTING BRACKET	10 TONNE AS BELOW AS ABOVE	61114
NONE LPL 210	LIFTING BRACKET FITTED TO TELESCOPE	7.5 TONNE AS BELOW AS ABOVE	62608
NONE LPL 211	LIFTING BRACKET FITTED TO TELESCOPE	7.5 TONNE AS BELOW AS ABOVE	62608
NONE LPL 212	LIFTING BRACKET FITTED TO TELESCOPE	7.5 TONNE AS BELOW AS ABOVE	62608
NONE LPL 213	LIFTING BRACKET FITTED TO TELESCOPE	7.5 TONNE AS BELOW AS ABOVE	62608
NONE LPL 226	RAILS AND STEELWORK (REV FLOOR)	44.45 TONNE AS BELOW AS ABOVE	LBT13315
NONE LW5 1160	LIFTING BRACKET	15 TONNE AS BELOW AS ABOVE	61114
NONE LPL 236	TIE ROD FITTED TO TELESCOPE	2 TON AS BELOW AS ABOVE	68335
NONE			

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

ENGINEER SUPERVISOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 5

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 237 TIE ROD FITTED TO TELESCOPE	2 TON AS BELOW AS ABOVE	RED 68335
NONE LPL 238 MIRROR LIFTING PLUG	2 TON AS BELOW AS ABOVE	68336
NONE LPL 239 MIRROR LIFTING SPIDER	18 TONNE AS BELOW AS ABOVE	63083
NONE LPL 029 3/4" LARGE BOW SHACKLE TO BS3032	25 CWT AS BELOW AS ABOVE	
NONE LPL 241 PRIM MIRROR HANDLING TROLLEY	37 TONNE AS BELOW AS ABOVE	LBT13314
NONE LPL 207 3/4" LARGE BOW SHACKLE TO BS3032	25 CWT AS BELOW AS ABOVE	
NONE LPL362 1/2" X 5/8" ALLOY STEEL DEE SHACKLE TO US FEDERAL SPEC RR-C-271B	2 TON AS BELOW AS ABOVE	28566
NONE LPL 246 TUBE TIE ROD ASSEMBLY	1.5 TONNE AS BELOW AS ABOVE	63078

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 6

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 247 TUBE TIE ROD ASSEMBLY	1.5 TONNE AS BELOW AS ABOVE	63079
NONE LPL 248 TUBE TIE ROD ASSEMBLY	1.5 TONNE AS BELOW AS ABOVE	63080
NONE LPL 249 TUBE TIE ROD ASSEMBLY	1.5 TONNE AS BELOW AS ABOVE	63081
NONE LPL 250 RISING PLATFORM	10.06 TONNE AS BELOW AS ABOVE	5/1580
NONE LPL 705 -569614 WIRE ROPE 5MT	10.06 TONNE AS BELOW AS ABOVE	5/1580
KINKED BUT SERVICEABLE LPL 706 -569614 WIRE ROPE 5MT	10.06 TONNE AS BELOW AS ABOVE	5/1580
KINKED BUT SERVICEABLE LPL 255 WIRE ROPE 5MT	10.06 TONNE AS BELOW AS ABOVE	5/1580
KINKED BUT SERVICEABLE LPL 272 HANDLING FRAME	800 KGS AS BELOW AS ABOVE	64837
NONE		

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

ENGINEER SUPERVISOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 7

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE RED
LPL 340 2" WIDE X 2MT WEBBING SLING NONE	1 TONNE AS BELOW AS ABOVE	14991
LPL 341 2" WIDE X 2MT WEBBING SLING NONE	1 TONNE AS BELOW AS ABOVE	14991
LPL 343 2" WIDE X 2MT WEBBING SLING NONE	1 TONNE AS BELOW AS ABOVE	14991
LPL 382 (A2) M16 COLLARED EYEBOLT NONE	0.8 TONNE AS BELOW AS ABOVE	55909
LPL 384 (A2) M16 COLLARED EYEBOLT NONE	0.8 TONNE AS BELOW AS ABOVE	55909
LPL 393 (A4) M20 COLLARED EYEBOLT NONE	1.6 TONNE AS BELOW AS ABOVE	55909
LPL 394 (A4) M20 COLLARED EYEBOLT NONE	1.6 TONNE AS BELOW AS ABOVE	55909
LPL 395 (A4) M20 COLLARED EYEBOLT NONE	1.6 TONNE AS BELOW AS ABOVE	55909

I certify that on 25.09.00 - 02.10.00 I carried out a thorough examination of the lifting tackle stated above and that this is a correct report of the result.

Signature  Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier
Address

ISAAC NEWTON GROUP OF TELESCOPES
LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 08

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 396 (A4) M20 COLLARED EYEBOLT	1.6 TONNE AS BELOW	55909
NOT LOCATED (2)	AS ABOVE	
LPL 403A KONE HOIST UNIT	2.5 TONNE AS BELOW	204/82
NONE	AS ABOVE	
LPL 425 1594/A LPL424 ISIS EQUIPMENT C/W 2 FABRICATED LIFTING FRAMES WITH ANCILLARY EQUIPMENT	3 TONNE AS BELOW	191487/1
NONE	AS ABOVE	
LPL 426 A AND G TRANSPORTER	2 TONNE AS BELOW	191487/1
NONE	AS ABOVE	
LPL 427 A AND G TRANSPORTER	2 TONNE AS BELOW	191487
NONE	AS ABOVE	
LPL 428 4 LEG WIRE SLING FITTED TO LPL 426/7	2.5 TONNE AT 90 DEG AS BELOW	191487
NONE	AS ABOVE	
LPL 429 3/4" LARGE BOW SHACKLE FITTED TO LPL 426/7	2 TON AS BELOW	191487
NONE	AS ABOVE	
LPL 430 3/4" LARGE BOW SHACKLE FITTED TO LPL 426/7	2 TON AS BELOW	191487
NONE	AS ABOVE	

I certify that on 25.09.00 -02.10.00
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPELDRE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552


REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 09

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE RED
LPL 431 NONE	3/4" LARGE BOW SHACKLE FITTED TO LPL 426/7 2 TON AS BELOW AS ABOVE	191487
LPL 432 NONE	3/4" LARGE BOW SHACKLE FITTED TO LPL 426/7 2 TON AS BELOW AS ABOVE	191487
LPL 433 NONE	1/2" LARGE BOW SHACKLE FITTED TO LPL 426/7 1 TON AS BELOW AS ABOVE	191487
LPL 442 NONE	M20 COLLARED EYEBOLT FITTED TO LPL 426/7 1.6 TONNE AS BELOW AS ABOVE	191487
LPL 443 NONE	M20 COLLARED EYEBOLT FITTED TO LPL 426/7 1.6 TONNE AS BELOW AS ABOVE	191487
LPL 444 NONE	M20 COLLARED EYEBOLT FITTED TO LPL 426/7 1.6 TONNE AS BELOW AS ABOVE	191487
LPL 450 3585 NONE	DEMAG O.E.T.C. F/W WIRE ROPE HOIST 2 TONNE AS BELOW AS ABOVE	191487
LPL 466 NONE	WEBER HYDRAULIC ENGINE CRANE 500 KGS AS BELOW AS ABOVE	988690

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature 

Qualification..... ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 10

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE RED
LPL 469 4 POINT SPREADER BEAM NONE	8 TONNE AS BELOW AS ABOVE	TC2698
LPL 471 STAINLESS STEEL OVERHEAD RUNWAY TRACK NO LONGER IN PLACE	150 KGS AS BELOW AS ABOVE	42606
LPL 472 EASTMAN HAND CHAIN HOIST NO LONGER IN PLACE	150 KGS AS BELOW AS ABOVE	191487
LPL 434 1/2" SMALL BOW SHACKLE FITTED TO LPL 426/7 NONE	1 TON AS BELOW AS ABOVE	191487
LPL 435 1/2" SMALL BOW SHACKLE FITTED TO LPL 426/7 NONE	1 TON AS BELOW AS ABOVE	191487
LPL 436 1/2" SMALL BOW SHACKLE FITTED TO LPL 426/7 NONE	1 TON AS BELOW AS ABOVE	191487
LPL 437 WIRE ROPE SLING FITTED TO LPL 426/7 NONE	1.25 TONNE AS BELOW AS ABOVE	191487
LPL 438 WIRE ROPE SLING FITTED TO LPL 426/7 NONE	1.25 TONNE AS BELOW AS ABOVE	988690

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature



Qualification

ENGINEER SURVEYOR