

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Tel: 01222 559522 Fax: 01222 559553

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS 1

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 003 (PL273) 20MM DIA WIRE ROPE SLING 3M SEEE NONE	4 TON AS BELOW AS ABOVE	RED Y3
LPL 004 (P273) 20MM DIA WIRE ROPE SLING 3M SEEE NONE	4 TON AS BELOW AS ABOVE	Y4
LPL 006 (PL272) 13MM DIA WIRE ROPE SLING 5'0" SEEE NONE	2 TON AS BELOW AS ABOVE	M13
LPL 007 (PL272) 13MM DIA WIRE ROPE SLING 5'0" SEEE NONE	2 TON AS BELOW AS ABOVE	M14
LPL 022 (10/1358) 1" DIA WIRE ROPE SLING 11" TEEE NONE	6 TON AS BELOW AS ABOVE	10/13958/ WQ130
LPL 023 (3W2266) 22MM WIRE ROPE SLING 25' TEEE / KINKED BUT SERVICEABLE	4 TON AS BELOW AS ABOVE	10/ 3W2266
LPL 091 (CB/204161) WIRE ROPE SLING 11M EWL	5.74 TON AS BELOW	NS1726

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA GARAGE STORES GS 2

Distineuishing number and descption

Safe working load

COLOUR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS 3

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 152 (17033) WIRE ROPE 0.95M NONE	5.14 TONNE AS BELOW AS ABOVE	3/0308A OO153.83
LPL 153 (17034) WIRE ROPE 0.95M 15" TEE	5.14 TONNE AS BELOW AS ABOVE	3/0308A OO153.83
LPL 154 (17035) WIRE ROPE 0.95M NONE	5.14 TONNE AS BELOW AS ABOVE	3/0308A OO153.83
LPL 160 (17041) WIRE ROPE 8.79M NONE	13.1 TONNE AS BELOW AS ABOVE	16/00152
LPL 161 (17042) WIRE ROPE 8.79M NONE	13.1 TONNE AS BELOW AS ABOVE	16/00152
LPL 162 (17043) WIRE ROPE 8.79M NONE	13.1 TONNE AS BELOW AS ABOVE	16/00152
LPL 164 (17045) WIRE ROPE 1.73M NONE	10.06 TONNE AS BELOW AS ABOVE	5/1897

EUROLIFTING

GRIFFIN FARM, APPELDRE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552


REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS4

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 166 (17047) WIRE ROPE 1.73M NONE	10.06 TONNE AS BELOW AS ABOVE	5/1879
LPL 167 (17048) WIRE ROPE 1.73M NONE	10.06 TONNE AS BELOW AS ABOVE	5/1897
LPL 172 (34011) 1.5/8" SMALL DEE SHACKLE TO BS3032 NONE	13 TON AS BELOW AS ABOVE	29392
LPL 173 (34013) 1.5/8" SMALL DEE SHACKLE TO BS3032 NONE	13 TON AS BELOW AS ABOVE	29392
LPL 174 (34013) 1.5/8" SMALL DEE SHACKLE TO BS3032 NONE	13 TON AS BELOW AS ABOVE	29392
LPL 175 (34014) 1.5/8" SMALL DEE SHACKLE TO BS3032 NONE	13 TON AS BELOW AS ABOVE	29392
LPL 186 (34023) 1.1/2" SMALL DEE SHACKLE TO BS3032 NONE	10.3/4 TON AS BELOW AS ABOVE	27924
LPL 187 (34024) 1.1/2" SMALL DEE SHACKLE NONE	10.3/4 TON AS BELOW AS ABOVE	27924

I certify that on 25.09.00 - 02.10.00
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature 

Qualification ENGINEER SURVEYOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS 5

Distinguishing number and description
Defects and observations

Safe working load
Date of examination
Location

COLOUR
CODE
RED

AS BELOW

EUROLIFTING

GRIFFIN FARM, APPELDRE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES

Address LA PALMA GARAGE STORES GS 6

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 203 LIFTING BRACKET	2 TONNE AS BELOW AS ABOVE	RED 59773
NONE LPL 205 LIFTING BRACKET	2 TONNE AS BELOW AS ABOVE	59773
NONE LPL 206 - 41943 LIFTING BRACKET	5 TONNE AS BELOW AS ABOVE	62612
NONE LPL 207 - 41944 LIFTING BRACKET	5 TONNE AS BELOW AS ABOVE	62612
NONE LPL 208 - 41945 LIFTING BRACKET	5 TONNE AS BELOW AS ABOVE	62612
NONE LPL 209 - 41946 LIFTING BRACKET	5 TONNE AS BELOW AS ABOVE	62612
NONE	AS ABOVE	

EUROLIFTING

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS 7

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 216 LIFTING BRACKET	6 TONNE AS BELOW	RED 62161
NONE LPL 222 (58675) M20 COLLARED EYEBOLT STORES	AS ABOVE 1.25 TONNE AS BELOW	27471/ 97/270
NONE LPL 223 (A4) M20 COLLARED EYEBOLT STORES	AS ABOVE 1.25 TONNE AS BELOW	27471/ 97/270

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS 8

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 353 (K/274/3C) 13MM DIA WIRE ROPE SLING SEEE	2 TONNE AS BELOW	RED 8439
NONE	AS ABOVE	
LPL 531 VERLINDE COMBINED CHAIN HOIST AND TROLLEY	1000 KGS AS BELOW	
WHEEL BEARINGS ON TROLLEY REQUIRE ATTENTION	AS ABOVE	
LPL 532 VERLINDE COMBINED CHAIN HOIST AND TROLLEY	1000 KGS AS BELOW	
WHEEL BEARINGS ON TROLLEY REQUIRE ATTENTION	AS ABOVE	
WN57B LPL696 M52 COLLARED EYEBOLT	10 TONNE AS BELOW	
NONE	AS ABOVE	
5S6371 LPL687 8MM WIRE ROPE SLING 18" EWL SEEE	0.76 TONNE AS BELOW	TEST CERTI- FICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	
5S6571 LPL688 8MM WIRE ROPE SLING 18" EWL SEEE	0.76 TONNE AS BELOW	TEST CERTI- FICATE SHOULD BE HELD ON FILE
NONE	AS ABOVE	
16000/31 LPL689 8MM WIRE ROPE SLING 11" EWL SEEE	0.76 TONNE	TEST CERTI-

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01222 559733 Fax: 01222 559553

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS 9

Distinguishing number and description
Defects and observations

Safe working load
Date of examination
Location

COLOUR
CODE
RED

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS 10

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE RED
LPL 139 (41933) LIFTING ROD	19 TONNE AS BELOW	LW62655
NOT LOCATED (2) LPL 140 (41934) LIFTING ROD	AS ABOVE 19 TONNE AS BELOW	LW2656
NOT LOCATED (2) LPL 141 (41927) LIFTING ROD	AS ABOVE 19 TONNE AS BELOW	LW2653
NOT LOCATED (2) LPL 142 (41928) LIFTING ROD	AS ABOVE 19 TONNE AS BELOW	LW2654
NOT LOCATED (2) LPL 272 (LB105) LIFTING FRAME ASSEMBLY (COOLER)	AS ABOVE 1300 KGS AS BELOW	LW70354
NONE LPL 265 (LB96) BEAM 100	AS ABOVE 100 KGS AS BELOW	LW63082
NONE LPL 901 (6046) 7/8" DIA RIGGING SCREW EYE AND JAW	AS ABOVE 22 CWT AS BELOW	M93442/ 97
NONE LPL 902 (6046) 7/8" DIA RIGGING SCREW EYE AND JAW	AS ABOVE 22 CWT	M93442/ 97
NONE		

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA GARAGE STORES GS 11

Distinguishing number and description

Safe working load

COLOUR

1

Date of examination

CODE

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA GARAGE STORES GS 12

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 144 LIFTING BRACKET	15 TON	RED
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 150 LIFTING BRACKET	15 TON	
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 151 LIFTING BRACKET	15 TON	
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 158 LIFTING BRACKET	15 TON	
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 909 LIFTING BRACKET	500KG	TEST CERTIFICATE SHOULD BE HELD ON FILE
NONE	AS BELOW	
NONE	AS ABOVE	
V21252 VERLINDE TROLLEY	1 TONNE	
NONE	AS BELOW	
NONE	AS ABOVE	

EUROLIFTING

GRIFFIN FARM, APPLEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Address LA PALMA GARAGE STORES GS 13

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
V21252/3 VERLINDE TROLLEY	1 TONNE AS BELOW AS ABOVE	RED
NONE V21252/4 VERLINDE TROLLEY	1 TONNE AS BELOW AS ABOVE	
NONE LPL 534 7MM 2 LEG CHAIN SLING	1 TON AS BELOW	
NONE LPL 265 GANTRY FRAME	1 TON AS BELOW	