

# EUROLIFTING


GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
 Address LA PALMA ISAAC NEWTON TELESCOPE INT 1

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
3735 MATBRO TELESCOPIC FORK LIFT	2700 KGS	RED 2651
HOOTER FOR REVERSING + FLASHING LAMP SHOULD BE FITTED OFF SIDE FRONT INDICATOR LENSE BROKEN DAMAGE TO SEALS ON NEAR SIDE HYDRAULIC LOCKING PIN	AS BELOW  AS ABOVE	



NONE	AS BELOW	
LPL 118 (71535) RATCLIFF TAIL LIFT FITTED TO MERCEDES LORRY	AS ABOVE 1000 KGS	4837-029
NONE	AS BELOW	
LPL 024 (3W2266) 22MM WIRE ROPE SLING 25' TEE	AS ABOVE 4 TON	10/3W2266
NONE	AS BELOW	
LPL 088 (13599) PELLOBY POST MOUNTED SWING JIB	AS ABOVE 2 TONNE	13599
NONE	AS BELOW	
LPL 089 (10-1001-NC2) MORRIS 360 ELECTRIC CHAIN HOIST ON ABOVE	AS ABOVE 2 TONNE	13599
	AS BELOW	

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA ISAAC NEWTON TELESCOPE INT 2

Distinguishing number and description

Safe working load

COLOUR

Defects and observations

Date of examination

CODE

LPL 111	LIFTING BEAM WITH CENTRE LIFTING EYE AND 2 POINT LIFTING LUGS AT 34" CENTRES	320 KGS AS BELOW	2651
NONE		AS ABOVE	
LPL 124	KONE ELECTRIC WIRE ROPE HOIST WITH FIXED	5 TONNE	92792600



# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA ISAAC NEWTON TELESCOPE INT 4

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL824 T1388 MOBILE HYDRAULIC LIFTING TABLE  NONE	2000 KGS	RED
	AS BELOW	TEST CERTIFICATE SHOULD BE HELD ON FILE
	AS ABOVE	FILE
LPL826 TB 122405 CENTRE POINT PICK UP MIRROR SPIDER LIFT  NONE	5 TONNE	TEST
	AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
	AS ABOVE	FILE
901155 WESCO DRUM LIFTER MODEL DL55  NONE	800 KGS	TEST
	AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
	AS ABOVE	FILE
507849 STOCKA HAND PALLET TRUCK  NOT LOCATED	2300 KGS	TEST
	AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
	AS ABOVE	FILE

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA ISAAC NEWTON TELESCOPE INT 5

Distinguishing number and description  
Defects and observations

Safe working load  
Date of examination  
Location

COLOUR  
CODE

RED  
51908

LPL828 9597

LIFTING BEAM (SHUTTER WHEEL  
CONTROL)

300 KGS

AS BELOW

AS ABOVE

NONE

LPL707-E1177

GOODS CAGE  
108 X 151 X 105CM

500 KGS

AS BELOW

AS ABOVE

WHT

NONE

2 LOCATED ON UPPER SHUTTER DOOR  
2 LOCATED ON LOWER SHUTTER DOOR

AS BELOW

CERTIFICATE  
SHOULD BE

NONE  
LEFT HAND SIDE LOWER SHUTTER WIRE ROPE HAS BROKEN STRANDS  
CAUSE SHOULD BE INVESTIGATED AND RECTIFIED

AS ABOVE

HELD ON  
FILE