

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 16

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 431  HT LARGE BOW SHACKLE TO BS3032  NOT LOCATED (4)	2 TON  AS BELOW  AS ABOVE	RED 170/ 2530/F97

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

Name of occupier  
Address

ISAAC NEWTON GROUP OF TELESCOPES  
LA PALMA LIFTING TACKLE STORES LTS 17

Distinguishing number and description  
Defects and observations

Safe working load  
Date of examination  
Location

COLOUR  
CODE

RED  
O2038

LPL 458 (21752)

4M CIRC POLYESTER ROUND SLING

3000 KGS

O2038

NOT LOCATED (1)

AS ABOVE

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES

Address LA PALMA LIFTING TACKLE STORES LTS 18

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE	
LPL 470 (97330)	3M CIRC POLYESTER ROUND SLING	2 TONNE	RED
NONE		AS BELOW	CERTIFICATE SHOULD BE HELD ON FILE
LPL 473	1" WHIT COLLARED EYEBOLT	2 TONNE	
NONE		AS ABOVE	
LPL 474	1" WHIT COLLARED EYEBOLT	2 TONNE	53462
NONE		AS BELOW	53462
LPL 474	1" WHIT COLLARED EYEBOLT	2 TONNE	
NONE		AS ABOVE	
LPL 475	1" WHIT COLLARED EYEBOLT	2 TONNE	53462
NONE		AS BELOW	53462
LPL 476	1" WHIT COLLARED EYEBOLT	2 TONNE	
NONE		AS ABOVE	
LPL 477	7/8" WHIT COLLARED EYEBOLT	2 TONNE	53462
NONE		AS BELOW	53462
LPL 478	7/8" WHIT COLLARED EYEBOLT	2 TONNE	
NONE		AS ABOVE	
LPL 479	7/8" WHIT COLLARED EYEBOLT	2 TONNE	53462
NONE		AS BELOW	53462
		AS ABOVE	

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature

Qualification

ENGINEER SURVEYOR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LT19

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 480	7/8" WHIT COLLARED EYEBOLT	RED
NONE	AS BELOW	53462
LPL 481	3/4" WHIT COLLARED EYEBOLT	AS ABOVE
NONE	AS BELOW	53462
LPL 482	3/4" WHIT COLLARED EYEBOLT	AS ABOVE
NONE	AS BELOW	53462
LPL 483	3/4" WHIT COLLARED EYEBOLT	AS ABOVE
NONE	AS BELOW	53462
LPL 484	5/8" WHIT COLLARED EYEBOLT	AS ABOVE
NONE	AS BELOW	53462
NONE	AS ABOVE	

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 20

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE	
LPL 488	1/2" WHIT COLLARED EYEBOLT	0.5 TONNE	RED 53462
		AS BELOW	
NONE		AS ABOVE	
LPL 489	1/2" WHIT COLLARED EYEBOLT	0.5 TONNE	53462
		AS BELOW	
NOT LOCATED ( 1 )		AS ABOVE	
LPL 490	1/2" WHIT COLLARED EYEBOLT	0.5 TONNE	53462
		AS BELOW	
NOT LOCATED ( 5 )		AS ABOVE	
LPL 493	3/8" WHIT COLLARED EYEBOLT	250 KGS	53462
		AS BELOW	
NOT LOCATED ( 5 )		AS ABOVE	
LPL 494	3/8" WHIT COLLARED EYEBOLT	250 KGS	53462
		AS BELOW	
NOT LOCATED ( 5 )		AS ABOVE	
LPL 495	3/8" WHIT COLLARED EYEBOLT	250 KGS	53462
		AS BELOW	
NOT LOCATED ( 5 )		AS ABOVE	
LPL 497 (012794)	6M CIRC POLYESTER ROUND SLING	2 TONNE	TEST CERTI-

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Distinguishing number and description  
Defects and observations

Safe working load  
Date of examination  
Location

COLOUR  
CODE

RED

LPL 499

5M CIRC POLYESTER ROUND SLING

2 TONNE

TEST CERTIFICATE  
SHOULD BE  
HELD ON

AS BELOW

NONE

AS ABOVE

FILE

LPL 499A

8MM DIA WIRE ROPE SLING  
C/W SEEE

500 KGS

44815

AS BELOW

NOT LOCATED ( 6 )

AS ABOVE

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occunier

ISAAC NEWTON GROUP OF TELESCOPES

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 504 M16 COLLARED EYEBOLT	0.8 TONNE AS BELOW	RED 44815
NONE LPL 505 M16 COLLARED EYEBOLT	AS ABOVE 0.8 TONNE AS BELOW	44815
NONE LPL 506 3/8" SMALL DEE SHACKLE TO BS3032	AS ABOVE 0.8 TONNE	44815

NOT LOCATED ( 6 ) LPL 529 VERLINDE CHAIN HOIST	AS BELOW AS ABOVE 1000 KGS AS BELOW	
NONE O12794 6M CIRC POLYESTER ROUNDSLING	AS ABOVE 2 TONNE AS BELOW	TEST CERTI- FICATE SHOULD BE FIELD ON

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE


Name of occupier ISAAC NEWTON GROUP OF TELESCOPES  
Address LA PALMA LIFTING TACKLE STORES LTS 23

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
1 X SET DORVIC SHIFTING SKATES C/W TURNTABLES, EQUALISERS, CROSSBARS AND HANDLES	40 TON PER SET OF 4 AS BELOW	RED
NOT LOCATED LPL897 844526	AS ABOVE 2000 KGS	
	IN W.H.T.	AS BELOW
NONE O1685	AS ABOVE 50 TONNE	TEST CERTI- FICATE SHOULD BE HELD ON FILE
HANDLE MISSING, DAMAGE TO SCREW EXTENSION O1686	AS BELOW 30 TONNE	TEST CERTI- FICATE SHOULD BE HELD ON FILE
HANDLE MISSING O1687	AS ABOVE 30 TONNE	TEST CERTI- FICATE SHOULD BE HELD ON FILE
HANDLE MISSING LPL962 30082	AS BELOW SWL N/A	
	AS ABOVE BOTTLE JACK	
	AS BELOW SWL 2 TON	
NONE LPL814	AS ABOVE 15 TONNE CAPACITY PER SET OF 4 AS BELOW AS ABOVE	
NONE		

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

Signature.....



Qualification.....

ENGINEER SURVEYOR

# EUROLIFTING

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 24

Distinguishing number and description

Safe working load

COLOUR  
CODE

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Address

LA PALMA LIFTING TACKLE STORES LTS 25

Distinonishing number and descption

Safe working load

COLOUR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 26

Distinguishing number and description  
Defects and observations

Safe working load  
Date of examination  
Location

COLOUR  
CODE

RED  
44815

IP 508

3/8" WHIT COLLARED EYEBOLT

5 CWT

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 27

Distinguishing number and description

Safe working load

COLOUR

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier  
Address

ISAAC NEWTON GROUP OF TELESCOPES  
LA PALMA LIFTING TACKLE STORES LTS 28

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
LPL 557 8M CIRC POLYESTER ROUNDSLING	3 TONNE AS BELOW	RED 3233
NOT LOCATED ( 1 ) LPL 558 6M CIRC POLYESTER ROUNDSLING	AS ABOVE 3 TONNE AS BELOW	3233
NONE LPL 559 6M CIRC POLYESTER ROUNDSLING	AS ABOVE 3 TONNE AS BELOW	3233
NOT LOCATED ( 2 ) LPL 560 6M CIRC POLYESTER ROUNDSLING	AS ABOVE 3 TONNE AS BELOW	3233
NONE LPL 561 6M CIRC POLYESTER ROUNDSLING	AS ABOVE 3 TONNE	3233

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

# EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

## REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 30

Distinguishing number and description Defects and observations		Safe working load Date of examination Location	COLOUR CODE
LPL 573	2M CIRC POLYESTER ROUND SLING	1 TONNE AS BELOW AS ABOVE	RED 3233
NOT LOCATED (2) LPL 574	2M CIRC POLYESTER ROUND SLING	1 TONNE AS BELOW AS ABOVE	3233
NONE EPL288 RG 3417	3 LEG WIRE ROPE SLING	3 TONNE AS BELOW AS ABOVE	
DUPLICATED			
NONE 15742	6M CIRC POLYESTER ROUND SLING	3 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NOT LOCATED (2) 14800	6M CIRC POLYESTER ROUND SLING	3 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE