

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 31

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
O131 2M CIRC POLYESTER ROUND SLING	1 TONNE AS BELOW AS ABOVE	RED
SCRAPED LPL822 R139205 01603 SUPER CLAMP	1 TONNE AS BELOW AS ABOVE	HEY13891
NONE LPL821 R139205 01604 SUPER CLAMP	1 TONNE AS BELOW AS ABOVE	HEY13886
NONE 14809 6M CIRC POLYESTER ROUND SLING	3 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NONE 99703 1/2" LARGE DEE SHACKLE TO BS3032	15 CWT AS BELOW AS ABOVE	
NOT LOCATED (2) SH265 ALLOY STEEL DEE SHACKLE TO US SPEC	2 TON AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NOT LOCATED (2) 127MA M16 COLLARED EYEBOLT	0.63 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NONE 12819 4M CIRC POLYESTER ROUND SLING	2 TONNE AS BELOW	TEST CERT- IFICATE SHOULD BE HELD ON

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 31

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
O131 2M CIRC POLYESTER ROUNDSLING	1 TONNE AS BELOW AS ABOVE	RED
SCRAPED LPL822 R139205 01603 SUPER CLAMP	1 TONNE AS BELOW AS ABOVE	HEY13891
NONE LPL821 R139205 01604 SUPER CLAMP	1 TONNE AS BELOW AS ABOVE	HEY13886
NONE 14809 6M CIRC POLYESTER ROUNDSLING	3 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NONE 99703 1/2" LARGE DEE SHACKLE TO BS3032	15 CWT AS BELOW AS ABOVE	
NOT LOCATED (2) SH265 ALLOY STEEL DEE SHACKLE TO US SPEC	2 TON AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NOT LOCATED (2) 127MA M16 COLLARED EYEBOLT	0.63 TONNE AS BELOW AS ABOVE	TEST CERT- IFICATE SHOULD BE HELD ON FILE
NONE 12819 4M CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW	TEST CERT- IFICATE SHOULD BE HELD ON

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 33

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR
		CODE
0131 2M CIRC POLYESTER ROUNDSLING	1 TONNE AS BELOW AS ABOVE	RED
DUPLICATED LPL698 15048 1M CIRC POLYESTER ROUNDSLING	2 TONNE AS BELOW AS ABOVE	
NONE LPL695 123437 POLYESTER ROUNDSLING	1 TONNE AS BELOW AS ABOVE	
NONE LPL690 6M CIRC POLYESTER ROUNDSLING	3 TONNE	TEST CERT-

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

I.A PALMA LIFTING TACKLE STORES LTS 34

Distinguishing number and description Defects and observations			Safe working load Date of examination Location	COLOUR CODE
LPL876	GER23	BOTTLE SCREW	7.5 CWT AS BELOW	RED
NONE			AS ABOVE	
LPL883	GER23	BOTTLE SCREW	7.5 CWT AS BELOW	

RUDOLPH TITING

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 35

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL916 BCG 33 H.T. SAFETY BOW SHACKLE TO BS3032 C/W NUT BOLT & SPLIT PIN	1 TON	

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 36

Distinguishing number and description Defects and observations		Safe working load Date of examination Location	COLOUR CODE RED
LPL872	8281	H.T. SAFETY BOW SHACKLE TO BS3032 C/W NUT BOLT & SPLIT PIN	2 TON AS BELOW AS ABOVE
NONE			
LPL873	8282	H.T. SAFETY BOW SHACKLE TO BS3032 C/W NUT BOLT & SPLIT PIN	2 TON AS BELOW AS ABOVE
NONE			
LPL874	8283	H.T. SAFETY BOW SHACKLE TO BS3032 C/W NUT BOLT & SPLIT PIN	2 TON AS BELOW AS ABOVE
NONE			
LPL875	8284	H.T. SAFETY BOW SHACKLE TO BS3032 C/W NUT BOLT & SPLIT PIN	2 TON AS BELOW AS ABOVE
NONE			
LPL920	CE 828	H.T. SAFETY BOW SHACKLE TO BS3032 C/W NUT BOLT & SPLIT PIN	1.5 TON AS BELOW AS ABOVE
NONE			
LPL921	CE 828	H.T. SAFETY BOW SHACKLE TO BS3032 C/W NUT BOLT & SPLIT PIN	1.5 TON AS BELOW AS ABOVE
NONE			
LPL922	CE 828	H.T. SAFETY BOW SHACKLE TO BS3032	1.5 TON

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 37

Distinguishing number and description Defects and observations		Safe working load Date of examination Location	COLOUR CODE RED	
LPL852	E 1	M8 COLLARED EYEBOLT TO BS4278/1	0.15 TON AS BELOW AS ABOVE	7431
NONE				
LPL853	E 2	M8 COLLARED EYEBOLT TO BS4278/1	0.15 TON AS BELOW AS ABOVE	7431
NONE				
LPL854	E 3	M8 COLLARED EYEBOLT TO BS4278/1	0.15 TON AS BELOW AS ABOVE	7431
NONE				
LPL855	E 4	M8 COLLARED EYEBOLT TO BS4278/1	0.15 TON AS BELOW AS ABOVE	7431
NONE				
LPL856	E 5	M8 COLLARED EYEBOLT TO BS4278/1	1.5 TON AS BELOW AS ABOVE	7431
NONE				
LPL857	E 6	M8 COLLARED EYEBOLT TO BS4278/1	1.5 TON AS BELOW AS ABOVE	7431
NONE				
LPL858	E 7	M8 COLLARED EYEBOLT TO BS4278/1	1.5 TON AS BELOW AS ABOVE	7431
NONE				
LPL859	E 8	M8 COLLARED EYEBOLT TO BS4278/1	1.5 TON AS BELOW AS ABOVE	7431

I certify that on 25.09.00 - 02.10.00
examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 38

Distinguishing number and description
Defects and observations

Safe working load
Date of examination
Location

COLOUR
CODE

RED

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 39

Distinguishing number and description
Defects and observations

Safe working load
Date of examination
Location

COLOUR
CODE

RED

M12 COLLAPSED EVERETT TO RS4278/1

0.40 TONNES

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 40

Distinguishing number and description

Safe working load

COLOUR

Date of examination

CODE

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA LIFTING TACKLE STORES LTS 41

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL383 M16 COLLARED EYEBOLT TO BS4278/1	0.80 TONNES AS BELOW AS ABOVE	
NONE LPL674 M16 COLLARED EYEBOLT TO BS4278/1	0.80 TONNES AS BELOW AS ABOVE	
NOT LOCATED (1) 5/8" BSW COLLARED EYEBOLT TO BS529/1	0.90 TONS	

NONE LPL676 5/8" BSW COLLARED EYEBOLT TO BS529/1	AS ABOVE 0.90 TONS AS BELOW	
NONE LPL677 M16 COLLARED EYEBOLT TO BS4278/1	AS ABOVE 0.80 TONNES AS BELOW	

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA LIFTING TACKLE STORES LTS 42

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR	
		CODE	
LPL289	M16 COLLARED EYEBOLT TO BS4278/1	0.80 TONNES	RED
		AS BELOW	
NONE		AS ABOVE	
LPL520	M16 COLLARED EYEBOLT TO BS4278/1 LONG SHANK	0.80 TONNES	
		AS BELOW	
NOT LOCATED (1)		AS ABOVE	
LPL521	M16 COLLARED EYEBOLT TO BS4278/1 LONG SHANK	0.80 TONNES	
		AS BELOW	
NOT LOCATED (1)		AS ABOVE	
LPL578	M16 COLLARED EYEBOLT TO BS4278/1 LONG SHANK	0.80 TONNES	
		AS BELOW	
NONE		AS ABOVE	
LPL579	M16 COLLARED EYEBOLT TO BS4278/1 LONG SHANK	0.80 TONNES	
		AS BELOW	
NONE		AS ABOVE	
LPL680	M16 COLLARED EYEBOLT TO BS4278/1 LONG SHANK	0.80 TONNES	
		AS BELOW	
NOT LOCATED (2)		AS ABOVE	
LPL681	M16 COLLARED EYEBOLT TO BS4278/1 LONG SHANK	0.80 TONNES	
		AS BELOW	
NOT LOCATED (2)		AS ABOVE	
LPL307	M16 COLLARED EYEBOLT TO BS4278/1 LONGSHANK	0.80 TONNES	
		AS BELOW	
NONE		AS ABOVE	