

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Tel: 01222 559522 Fax: 01222 559553

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 1

Distinguishing number and description
Defects and observations

Safe working load
Date of examination
Location

COLOUR
CODE

RED

60416

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA


Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier
Address

ISAAC NEWTON GROUP OF TELESCOPES
LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 2

Distinguishing number and description Defects and observations		Safe working load Date of examination Location	COLOUR CODE RED
LPL 130 (LB95)	LIFTING BEAM	45 TONNE AS BELOW AS ABOVE	LW62648
NOT LOCATED LPL 131	LIFTING PIN	22.50 TONNE AS BELOW AS ABOVE	LW2661
NOT LOCATED LPL 132	LIFTING PIN	22.50 TONNE AS BELOW AS ABOVE	LW2661



NOT LOCATED LPL 134	LIFTING PIN	AS BELOW AS ABOVE 22.50 TONNE AS BELOW AS ABOVE	LW2661
NOT LOCATED LPL 151 (17032)	WIRE ROPE 0.95M	5.14 TONNE	3/0308A001

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 4

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 199 LIFTING BRACKET NONE	10 TONNE AS BELOW AS ABOVE	61114
LPL 210 LIFTING BRACKET FITTED TO TELESCOPE NONE	7.5 TONNE AS BELOW AS ABOVE	62608
LPL 211 LIFTING BRACKET FITTED TO TELESCOPE NONE	7.5 TONNE AS BELOW AS ABOVE	62608
LPL 212 LIFTING BRACKET FITTED TO TELESCOPE NONE	7.5 TONNE AS BELOW AS ABOVE	62608
LPL 213 LIFTING BRACKET FITTED TO TELESCOPE NONE	7.5 TONNE AS BELOW AS ABOVE	62608
LPL 226 RAILS AND STEELWORK (REV FLOOR) NONE	44.45 TONNE AS BELOW AS ABOVE	LBT13315
LW5 1160 LIFTING BRACKET NONE	15 TONNE AS BELOW AS ABOVE	61114
LPL 236 TIE ROD FITTED TO TELESCOPE NONE	2 TON AS BELOW AS ABOVE	68335

I certify that on 25.09.00 - 02.10.00 examination of the lifting tackle stated above and that this is a correct report of the result.

I carried out a thorough

ENGINEER SUPERVISOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 5

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 237 TIE ROD FITTED TO TELESCOPE NONE	2 TON AS BELOW AS ABOVE	RED 68335
LPL 238 MIRROR LIFTING PLUG NONE	2 TON AS BELOW AS ABOVE	68336
LPL 239 MIRROR LIFTING SPIDER NONE	18 TONNE AS BELOW AS ABOVE	63083
LPL 029 3/4" LARGE BOW SHACKLE TO BS3032 NONE	25 CWT AS BELOW AS ABOVE	

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 6

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
LPL 247 TUBE TIE ROD ASSEMBLY	1.5 TONNE	RED 63079
NONE	AS BELOW	
	AS ABOVE	

EUROLIFTING

GRIFFIN FARM, APPELDRE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier

ISAAC NEWTON GROUP OF TELESCOPES

Address

LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 7

Serial, batch number and description

Safe working load

COLOR

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier
Address

ISAAC NEWTON GROUP OF TELESCOPES
LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 08

Distinguishing number and description
Defects and observations

Safe working load
Date of examination
Location

COLOUR
CODE

RED
55909

LPL 396

(A4) M20 COLLARED EYEBOLT

1.6 TONNE

AS BELOW

AS ABOVE

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

Name of occupier
Address

ISAAC NEWTON GROUP OF TELESCOPES
LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 09

Distinguishing number and description

Safe working load

COLOUR

Defects and observations

Date of examination

CODE

EUROLIFTING

GRIFFIN FARM, APPLIEDORE, KENT TN26 2BA

Telephone: 01233 758733 Fax: 01233 758552

REPORT OF EXAMINATION OF CHAINS, ROPES AND LIFTING TACKLE

Name of occupier ISAAC NEWTON GROUP OF TELESCOPES
 Address LA PALMA WILLIAM HERSCHEL TELESCOPE WHT 10

Distinguishing number and description Defects and observations	Safe working load Date of examination Location	COLOUR CODE
		RED
LPL 469 4 POINT SPREADER BEAM	8 TONNE AS BELOW	TC2698
NONE	AS ABOVE	
LPL 471 STAINLESS STEEL OVERHEAD RUNWAY TRACK	150 KGS AS BELOW	42606
NONE	AS ABOVE	
NO LONGER IN PLACE LPL 472 EASTMAN HAND CHAIN HOIST	150 KGS	191487

NONE	AS BELOW	
NO LONGER IN PLACE	AS ABOVE	
LPL 434 1/2" SMALL BOW SHACKLE FITTED TO LPL 426/7	1TON	191487
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 435 1/2" SMALL BOW SHACKLE FITTED TO LPL 426/7	1 TON	191487
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 436 1/2" SMALL BOW SHACKLE FITTED TO LPL 426/7	1 TON	191487
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 437 WIRE ROPE SLING FITTED TO LPL 426/7	1.25 TONNE	191487
NONE	AS BELOW	
NONE	AS ABOVE	
LPL 438 WIRE ROPE SLING FITTED TO LPL 426/7	1.25 TONNE	988690
NONE	AS BELOW	
NONE	AS ABOVE	

I certify that on

25.09.00 - 02.10.00

I carried out a thorough